

Dated: 24.03.2025

Sub: Commissioning inspection of Loco No. 38856 equipped with M/S Hind Rectifiers limited make prototype IGBT based 3-phase drive Propulsion Equipment

Ref:

- i. CLW PO No. 70211134D01496 dated 28.10.2021
- ii. CLW letter no. C-D&D/T/24(Part-IV)/Hirect dated 21.09.2024

Members Present:







CLW Representatives	BLEE Shed Representatives	M/S HIRECT Representatives
Mr. Ankit Kumar Verma SSE/D&D/CLW	Mr. Ashish Kumar Rathore SSE/TRS/BLEE	Mr. Kshaunish Kayal Manager/Hirect
Mr. Jitendra Singh JE/D&D/CLW	Mr. Pravin Panchal JE/TRS/BLEE	Mr. Jitendra Singh Manager/Hirect

Vide reference to the above, Loco No. 38856 has been fitted with prototype Propulsion Equipment of M/S Hind Rectifiers Limited Make and same is under commissioning at CLW/CRJ.

The Locomotive functionality has been tested jointly with CLW/C-D&D, BLEE Shed representatives & firm representatives and all functionality tests report have been appended in attached annexures below:

Annexures:




- Annexure 1 : Analogue Signal Checking
 Annexure 2 : Functional Test in Simulation Mode
 Annexure 3 : Protective Functions in WAG9 locomotive
 Annexure 4 : Performance Test

 Mr. Ankit Verma SSE/D&D/CLW/CRJ	 Mr. Jitendra Singh Manager/R&D Hind Rectifiers Ltd.	 Mr. Ashish Kumar Rathore SSE/TRS/BLEE	 Mr. Kshaunish Kayal Manager/R&D Hind Rectifiers Ltd.	 Mr. Pravin Panchal JE/TRS/BLEE	 Mr. Jitendra Singh JE/D&D/CLW/CRJ
---	---	--	--	---	---





Analogue Signal Checking (Testing & Commissioning Format for 3-Phase Locomotive fitted with IGBT based Traction Converter, Auxiliary Converter and VCU Format No. F60.305.01, Version:06)
Check for the following analogue signals with the help of DDU/firm's laptop and same to be Verified OK by the testing supervisor connected with loco.

Description	Prescribed value	Functional Requirement ^t	Observations and Value displayed on DDU	Remark	Photo
Brake pipe pressure	100% (= 5 Kg/cm ²)	Displayed value of BP on DDU should be changed after application of A9 brake according to Analog BP Gauge reading	Checked in both simulation and in Power mode In loco running condition at 596 node when A9 brake handle was at RUN position, 5 Kg/cm ² BP was observed	Verified OK	



	Mr. Ankit Verma SSE/D&D/CLW/CRJ		Mr. Jitendra Singh Manager/R&D Hind Rectifiers Ltd.		Mr. Ashish Kumar Rathore SSE/TRS/BLEE		Mr. Kshaunish Kayal Manager/R&D Hind Rectifiers Ltd.		Mr. Pravin Panchal JE/TRS/BLEE		Mr. Jitendra Singh JE/D&D/CLW/CRJ
---	------------------------------------	---	---	---	--	---	--	---	-----------------------------------	---	--------------------------------------

Actual BE electric	100% (= 10V)	Displayed value of BE on DDU should be changed according to Analog BE Gauge reading.	Checked in simulation mode In this condition at 596 node when regenerative braking was taken by moving throttle in BE side	258.6 KN BE, (130 KN per bogie) was observed. (also mapped with other values of BE Gauge reading)	Verified OK	
TE/BE at '0' position from both cab	Between 0% and 10% of Max KN	Observed values should be within prescribed range	0%	Verified OK		
TE/BE at 'TE maximal'	Between 95% and 105% of Max KN	TE Calculated by formula =	100%	Verified OK		

					
Mr. Ankit Verma SSE/D&D/CLW/CRL	Mr. Jitendra Singh Manager/R&D Hind Rectifiers Ltd.	Mr. Ashish Kumar Rathore SSE/TRS/BLEE	Mr. Kshaunish Kayal Manager/R&D Hind Rectifiers Ltd.	Mr. Pravin Panchal JE/TRS/BLEE	Mr. Jitendra Singh JE/D&D/CLW/CRL







position from both cab		(actual TE of both bogie x 100) /504kN	(504kN value is observed in simulation mode.)		 
TE/BE at 'TE minimal' position from both cab	Between 10% and 33% of Max kN		10.8% (54.9 kN observed in simulation mode)	Verified OK	 



					
Mr. Ankit Verma SSE/D&D/CLW/CRI	Mr. Jitendra Singh Manager/R&D Hind Rectifiers Ltd.	Mr. Ashish Kumar Rathore SSE/TRS/BLEE	Mr. Kshaunish Kayal Manager/R&D Hind Rectifiers Ltd.	Mr. Pravin Panchal JE/TRS/BLEE	Mr. Jitendra Singh JE/D&D/CLW/CRI



TE/BE at 'BE maximal' position from both cab	Between 95% and 105% of Max KN		99.5% (258.7 KN observed in simulation mode)	Verified OK	
TE/BE at 'BE Minimal' position from both cab	Between 10% and 33% of Max KN		12.26% (31.9 KN observed in simulation mode)	Verified OK	


	Mr. Ankit Verma SSE/D&D/CLW/CRJ		Mr. Jitendra Singh Manager/R&D Hind Rectifiers Ltd.		Mr. Ashish Kumar Rathore SSE/TRS/BLEE		Mr. Kshaunish Kayal Manager/R&D Hind Rectifiers Ltd.		Mr. Pravin Panchal JE/TRS/BLEE		Mr. Jitendra Singh JE/D&D/CLW/CRJ
---	------------------------------------	---	---	--	--	---	--	---	-----------------------------------	---	--------------------------------------

TE/BE at '1/3 position' in TE and BE mode in both cab	Between 33% and 50% of Max KN		36.38% of BE (94.1 KN observed in simulation mode) 33.15% (167 KN observed in Simulation mode)	Verified OK	

 Mr. Ankit Verma SSE/D&D/CLW/CRJ	 Mr. Jitendra Singh Manager/R&D Hind Rectifiers Ltd.	 Mr. Ashish Kumar Rathore SSE/TRS/BLEE	 Mr. Kshanaish Kayal Manager/R&D Hind Rectifiers Ltd.	 Mr. Pravish Panchal JE/TRS/BLEE	 Mr. Jitendra Singh JE/D&D/CLW/CRJ
---	--	--	---	---	---

TE/BE at '2/3 position' in TE and BE mode in both cab	Between 51% and 75% of Max kN		75% of TE (381 kN observed in simulation mode) 71% of BE (184.3 kN observed in simulation mode)	Verified OK	 
Both temperature sensor of TM1	Between 10% to 14.33% depending upon ambient	Observed values should be within	Checked in traction mode When loco was stand still at 570 node	Verified OK	

					
Mr. Ankit Verma SSE/D&D/CLW/CRJ	Mr. Jitendra Singh Manager/R&D Hind Rectifiers Ltd.	Mr. Ashish Kumar Rathore SSE/TRS/BLEE	Mr. Kshaunish Kayal Manager/R&D Hind Rectifiers Ltd.	Mr. Pravln Panchal JE/TRS/BLEE	Mr. Jitendra Singh JE/D&D/CLW/CRJ

	temperature 0°C to 50°C	prescribed range	23.57 °C @ 23 °C amb		 <p>The screenshot shows the locomotive's digital display. At the top, it displays 'Mode Information' with fields for FL61 (570), FL62 (570), SILV (0), SIL61 (3099), SIL62 (3099), ESM (OFF), AL61 (178), AL62 (178), and SIMKEY (ON). Below this, there is a 'Temperature' section with a grid of values. The first row shows 23.57, 19.83, 20.55, 23.16, 21.55, and 21.49. The second row shows 0, 0, 0, 0, 0, and 0. The third row shows 0, 0, 0, 0, 0, and 0. The fourth row shows 0, 0, 0, 0, 0, and 0. The fifth row shows 0, 0, 0, 0, 0, and 0. The sixth row shows 0, 0, 0, 0, 0, and 0. The seventh row shows 0, 0, 0, 0, 0, and 0. The eighth row shows 0, 0, 0, 0, 0, and 0. The ninth row shows 0, 0, 0, 0, 0, and 0. The tenth row shows 0, 0, 0, 0, 0, and 0. The eleventh row shows 0, 0, 0, 0, 0, and 0. The twelfth row shows 0, 0, 0, 0, 0, and 0. The thirteenth row shows 0, 0, 0, 0, 0, and 0. The fourteenth row shows 0, 0, 0, 0, 0, and 0. The fifteenth row shows 0, 0, 0, 0, 0, and 0. The sixteenth row shows 0, 0, 0, 0, 0, and 0. The seventeenth row shows 0, 0, 0, 0, 0, and 0. The eighteenth row shows 0, 0, 0, 0, 0, and 0. The nineteenth row shows 0, 0, 0, 0, 0, and 0. The twentieth row shows 0, 0, 0, 0, 0, and 0. The twenty-first row shows 0, 0, 0, 0, 0, and 0. The twenty-second row shows 0, 0, 0, 0, 0, and 0. The twenty-third row shows 0, 0, 0, 0, 0, and 0. The twenty-fourth row shows 0, 0, 0, 0, 0, and 0. The twenty-fifth row shows 0, 0, 0, 0, 0, and 0. The twenty-sixth row shows 0, 0, 0, 0, 0, and 0. The twenty-seventh row shows 0, 0, 0, 0, 0, and 0. The twenty-eighth row shows 0, 0, 0, 0, 0, and 0. The twenty-ninth row shows 0, 0, 0, 0, 0, and 0. The thirtieth row shows 0, 0, 0, 0, 0, and 0. The thirty-first row shows 0, 0, 0, 0, 0, and 0. The thirty-second row shows 0, 0, 0, 0, 0, and 0. The thirty-third row shows 0, 0, 0, 0, 0, and 0. The thirty-fourth row shows 0, 0, 0, 0, 0, and 0. The thirty-fifth row shows 0, 0, 0, 0, 0, and 0. The thirty-sixth row shows 0, 0, 0, 0, 0, and 0. The thirty-seventh row shows 0, 0, 0, 0, 0, and 0. The thirty-eighth row shows 0, 0, 0, 0, 0, and 0. The thirty-ninth row shows 0, 0, 0, 0, 0, and 0. The fortieth row shows 0, 0, 0, 0, 0, and 0. The forty-first row shows 0, 0, 0, 0, 0, and 0. The forty-second row shows 0, 0, 0, 0, 0, and 0. The forty-third row shows 0, 0, 0, 0, 0, and 0. The forty-fourth row shows 0, 0, 0, 0, 0, and 0. The forty-fifth row shows 0, 0, 0, 0, 0, and 0. The forty-sixth row shows 0, 0, 0, 0, 0, and 0. The forty-seventh row shows 0, 0, 0, 0, 0, and 0. The forty-eighth row shows 0, 0, 0, 0, 0, and 0. The forty-ninth row shows 0, 0, 0, 0, 0, and 0. The fiftieth row shows 0, 0, 0, 0, 0, and 0. The fifty-first row shows 0, 0, 0, 0, 0, and 0. The fifty-second row shows 0, 0, 0, 0, 0, and 0. The fifty-third row shows 0, 0, 0, 0, 0, and 0. The fifty-fourth row shows 0, 0, 0, 0, 0, and 0. The fifty-fifth row shows 0, 0, 0, 0, 0, and 0. The fifty-sixth row shows 0, 0, 0, 0, 0, and 0. The fifty-seventh row shows 0, 0, 0, 0, 0, and 0. The fifty-eighth row shows 0, 0, 0, 0, 0, and 0. The fifty-ninth row shows 0, 0, 0, 0, 0, and 0. The sixtieth row shows 0, 0, 0, 0, 0, and 0. The sixty-first row shows 0, 0, 0, 0, 0, and 0. The sixty-second row shows 0, 0, 0, 0, 0, and 0. The sixty-third row shows 0, 0, 0, 0, 0, and 0. The sixty-fourth row shows 0, 0, 0, 0, 0, and 0. The sixty-fifth row shows 0, 0, 0, 0, 0, and 0. The sixty-sixth row shows 0, 0, 0, 0, 0, and 0. The sixty-seventh row shows 0, 0, 0, 0, 0, and 0. The sixty-eighth row shows 0, 0, 0, 0, 0, and 0. The sixty-ninth row shows 0, 0, 0, 0, 0, and 0. The seventieth row shows 0, 0, 0, 0, 0, and 0. The seventy-first row shows 0, 0, 0, 0, 0, and 0. The seventy-second row shows 0, 0, 0, 0, 0, and 0. The seventy-third row shows 0, 0, 0, 0, 0, and 0. The seventy-fourth row shows 0, 0, 0, 0, 0, and 0. The seventy-fifth row shows 0, 0, 0, 0, 0, and 0. The seventy-sixth row shows 0, 0, 0, 0, 0, and 0. The seventy-seventh row shows 0, 0, 0, 0, 0, and 0. The seventy-eighth row shows 0, 0, 0, 0, 0, and 0. The seventy-ninth row shows 0, 0, 0, 0, 0, and 0. The eightieth row shows 0, 0, 0, 0, 0, and 0. The eighty-first row shows 0, 0, 0, 0, 0, and 0. The eighty-second row shows 0, 0, 0, 0, 0, and 0. The eighty-third row shows 0, 0, 0, 0, 0, and 0. The eighty-fourth row shows 0, 0, 0, 0, 0, and 0. The eighty-fifth row shows 0, 0, 0, 0, 0, and 0. The eighty-sixth row shows 0, 0, 0, 0, 0, and 0. The eighty-seventh row shows 0, 0, 0, 0, 0, and 0. The eighty-eighth row shows 0, 0, 0, 0, 0, and 0. The eighty-ninth row shows 0, 0, 0, 0, 0, and 0. The ninetieth row shows 0, 0, 0, 0, 0, and 0. The ninety-first row shows 0, 0, 0, 0, 0, and 0. The ninety-second row shows 0, 0, 0, 0, 0, and 0. The ninety-third row shows 0, 0, 0, 0, 0, and 0. The ninety-fourth row shows 0, 0, 0, 0, 0, and 0. The ninety-fifth row shows 0, 0, 0, 0, 0, and 0. The ninety-sixth row shows 0, 0, 0, 0, 0, and 0. The ninety-seventh row shows 0, 0, 0, 0, 0, and 0. The ninety-eighth row shows 0, 0, 0, 0, 0, and 0. The ninety-ninth row shows 0, 0, 0, 0, 0, and 0. The hundredth row shows 0, 0, 0, 0, 0, and 0.</p>
Both temperature sensor of TM2	Between 10% to 14.33% depending upon ambient temperature 0°C to 50°C		Checked in traction mode When loco was stand still at 570 node	Verified OK	
Both temperature sensor of TM3	Between 10% to 14.33% depending upon ambient temperature 0°C to 50°C	Observed values should be within prescribed range	Checked in traction mode When loco was stand still at 570 node	Verified OK	
Both temperature sensor of TM4	Between 10% to 14.33% depending upon ambient temperature 0°C to 50°C		20.55 °C @ 23 °C amb Checked in traction mode When loco was stand still at 570 node	Verified OK	
Both temperature	Between 10% to 14.33% depending upon ambient		23.16 °C @ 23 °C amb Checked in traction mode	Verified OK	


	Mr. Ankit Verma SSE/D&D/CLW/CRJ		Mr. Jitendra Singh Manager/R&D Hind Rectifiers Ltd.		Mr. Ashish Kumar Rathore SSE/TRS/BLEE		Mr. Kshaunish Kayal Manager/R&D Hind Rectifiers Ltd.		Mr. Pravin Panchal JE/TRS/BLEE		Mr. Jitendra Singh JE/D&D/CLW/CRJ
---	------------------------------------	---	---	--	--	---	--	---	-----------------------------------	---	--------------------------------------







sensor of TM5	temperature 0°C to 50°C		When loco was stand still at 570 node		
Both temperature sensor of TM6	Between 10% to 14.33% depending upon ambient temperature 0°C to 50°C		21.55 °C @ 23 °C amb Checked in traction mode When loco was stand still at 570 node 21.4 °C @ 23 °C amb	Verified OK	


					
Mr. Ankit Verma SSE/D&D/CLW/CRJ	Mr. Jitendra Singh Manager/R&D Hind Rectifiers Ltd.	Mr. Ashish Kumar Rathore SSE/TRS/BLEE	Mr. Kshaunish Kayal Manager/R&D Hind Rectifiers Ltd.	Mr. Pravin Panchal JE/TRS/BLEE	Mr. Jitendra Singh JE/D&D/CLW/CRJ







Annexure: 2**Functional Test in Simulation Mode**



Conduct the following functional tests in simulation mode as per Para 5.5 of document no.3EHX 610 281 through the laptop/DDU:

Test Function	Test Procedure/ Functional Requirement	Test Procedure Followed	Observation	Result	Photo
Emergency shutdown through emergency stop switch 244	An Emergency braking operation can be initiated by actuation of the Emergency stop push button on A panel VCB must open. Pantograph must lower. Flasher light should glow TE should be zero	Push Emergency Shutdown button located on A panel in both active and inactive CAB	<p>Checked for both in loco energized condition and in simulation mode</p> <ul style="list-style-type: none"> Push emergency stop button in loco running condition at 596 node VCB opened Panto lowered Traction effort became zero BP pressure dropped BC applied In inactive CAB emergency stop button on A 	Verified OK	



	Mr. Ankit Verma SSE/D&D/CLW/CRJ		Mr. Jitendra Singh Manager/R&D Hind Rectifiers Ltd.		Mr. Ashish Kumar Rathore SSE/TRS/BLEE		Mr. Kshaunish Kayal Manager/R&D Hind Rectifiers Ltd.		Mr. Pravin Panchal JE/TRS/BLEE		Mr. Jitendra Singh JE/D&D/CLW/CRJ
---	------------------------------------	---	---	--	--	---	--	---	-----------------------------------	---	--------------------------------------

Test Function	Test Procedure/ Functional Requirement	Test Procedure Followed	Observation	Result	Photo
			panel was pressed in loco running condition at 596 node then emergency stop was not activated		
Shut Down through cab activation switch to "OFF" position	Move BL key from drive position to off position VCB must open. Panto must lower.	Moved BL key from drive position to off position	<p>Checked for both in loco energized condition and in simulation mode</p> <p>Moved BL key from D to Off position</p> <ul style="list-style-type: none"> • VCB opened • Pantograph lowered • Final node reached to 612 • Loco has gone in hold mode for 10 minute 	Verified OK.	In simulation mode


					
Mr. Ankit Verma SSE/D&D/CLW/CRJ	Mr. Jitendra Singh Manager/R&D Hind Rectifiers Ltd.	Mr. Ashish Kumar Rathore SSE/TRS/BLEE	Mr. Kshaurish Kayal Manager/R&D Hind Rectifiers Ltd.	Mr. Pravin Panchal JE/TRS/BLEE	Mr. Jitendra Singh JE/D&D/CLW/CRJ

Test Function	Test Procedure/ Functional Requirement	Test Procedure Followed	Observation	Result	Photo
			<p>Moved BL key from D to off position and off to C and then moved from C to off position and removed at off position from A panel</p> <ul style="list-style-type: none"> VCB opened node reached to 550 Pantograph lowered node reached to 504 Main control electronics shut down 		  <p>In energized condition</p>

					
Mr. Ankit Verma SSE/D&D/CLW/CRJ	Mr. Jitendra Singh Manager/R&D Hind Rectifiers Ltd.	Mr. Ashish Kumar Rathore SSE/TRS/BLEE	Mr. Kshaunish Kayal Manager/R&D Hind Rectifiers Ltd.	Mr. Pravin Panchal JE/TRS/BLEE	Mr. Jitendra Singh JE/D&D/CLW/CRJ







Test Function	Test Procedure/Functional Requirement	Test Procedure Followed	Observation	Result	Photo
Converter and filter contactor operation with both Power Converters during Start Up.	<p>FB contactor 8.41 is closed. By moving reverser handle or node ≥ 570(in case of M/s Siemens):</p> <ul style="list-style-type: none"> • Converter pre-charging contactor must close after few seconds. • Converter main contactor must close. 	DDU/HMI/Laptop was connected with VCU	<p>Checked in simulation mode from both CAB and Verified OK the status of contactor on DDU has been verified.</p> <p>After self-test when node reached to 504 then discharging contactor 8.41 was closed</p> <p>After closing VCB, when reverser was moved in reverse/forward direction at 570 node</p>	Verified OK	 



					
Mr. Ankit Verma SSE/D&D/CLW/CRJ	Mr. Jitendra Singh Manager/R&D Hind Rectifiers Ltd.	Mr. Ashish Kumar Rathore SSE/TRS/BLEE	Mr. Kshaunish Kayal Manager/R&D Hind Rectifiers Ltd.	Mr. Pravin Panchal JE/TRS/BLEE	Mr. Jitendra Singh JE/D&D/CLW/CRJ







Test Function	Test Procedure/ Functional Requirement	Test Procedure Followed	Observation	Result	Photo
	<ul style="list-style-type: none"> • Converter pre-charging contactor must open. By increasing TE/BE throttle: <ul style="list-style-type: none"> • FB contactor 8.41 must open. • FB contactor 8.2 must close. • FB contactor 8.1 must close. 		<p>then Precharge contactor 12.1 was closed and DC link was charged</p> <p>After few second converter main contactor 12.2 was closed and and Precharge contactor was opened</p> <p>After moving throttle node reached to 596 and FB contactor 8.41 was opened and 8.2 and 8.1 was closed</p>		
Converter and filter contactor operation with both Power Converters during Shut Down.	<p>Bring TE/BE to 'O' activation key to 'O'.</p> <ul style="list-style-type: none"> • VCB must open. • Pantio must lower. • Converter main contactor must open. • FB contactor 8.1 must open. 	<p>DDU/HMI/Laptop was connected with VCU</p> <p>Move BL key from 'D' to 'O'</p>	<p>Checked in simulation mode from both CAB and Verified OK the status of contactor on DDU has been verified.</p> <ul style="list-style-type: none"> • VCB opened. • Pantio lowered. 	Verified OK	


					
Mr. Ankit Verma SSE/D&D/CLW/CRJ	Mr. Jitendra Singh Manager/R&D Hind Rectifiers Ltd.	Mr. Ashish Kumar Rathore SSE/TRS/BLEE	Mr. Kshaunish Kayal Manager/R&D Hind Rectifiers Ltd.	Mr. Pravin Panchal JE/TRS/BLEE	Mr. Jitendra Singh JE/D&D/CLW/CRJ

Test Function	Test Procedure/ Functional Requirement	Test Procedure Followed	Observation	Result	Photo
Contactor filter adaptation by bogie	<ul style="list-style-type: none"> • FB contactors 8.41 must close. • FB contactor 8.2 must remain closed. 		<p>FB discharging contactor 8.41 is closed. Verified OK on DDU</p> <p>FB main contactor 8.1 opened and 8.2 had closed. Verified OK on DDU</p>	Verified OK	


 Mr. Ankit Verma SSE/D&D/CLW/CRJ	 Mr. Jitendra Singh Manager/R&D Hind Rectifiers Ltd.	 Mr. Ashish Kumar Rathore SSE/TRS/BLEE	 Mr. Kshaunish Kayal Manager/R&D Hind Rectifiers Ltd.	 Mr. Pravin Panchal JET/RS/BLEE	 Mr. Jitendra Singh JE/D&D/CLW/CRJ
---	---	---	---	--	---

Test Function	Test Procedure/ Functional Requirement	Test Procedure Followed	Observation	Result	Photo
	<ul style="list-style-type: none"> FB contactor 8.2 remains open. 		After closing VCB and taking traction 8.1 contactor had closed and 8.2 remained open		
Test earth fault detection battery circuit positive & negative	wire 2050 to earth, create earth fault negative potential. <ul style="list-style-type: none"> message for earth fault By connecting wire 2095 to earth, create earth fault positive potential. message for earth fault. 	Wire 2050 is earthed to the body for simulating negative earth fault Wire 2095 is earthed to the body for simulating positive earth fault	Earth fault battery circuit pop-up message appeared on DDU screen	Verified OK	


					
Mr. Ankit Verma SSE/D&D/CLW/CRU	Mr. Jitendra Singh Manager/R&D Hind Rectifiers Ltd.	Mr. Ashish Kumar Rathore SSE/TRS/BLEE	Mr. Kshaunish Kayal Manager/R&D Hind Rectifiers Ltd.	Mr. Pravin Panchal JE/TRS/BLEE	Mr. Jitendra Singh JE/D&D/CLW/CRU







Test Function	Test Procedure/ Functional Requirement	Test Procedure Followed	Observation	Result	Photo
Angle Transmitter Failure Mode	Failure mode should work when difference between auxiliary contacts and the absolute value of angle transmitter became greater	Disconnect EA connector of angle transmitter from VCU	Checked in simulation and traction mode from Both CAB Disconnected EA connector from VCU 1 when CAB 1 was	Verified OK	At 0< TE< 1/3TEmax
Test fire system. Create a smoke in the machine room near the FDU. Watch for activation of alarm.	When smoke sensor-1 gets activated then • Alarm triggers and fault message priority 2 appears on screen. When both smoke sensor 1+2 gets activated then • A fault message priority 1 appears on screen and lamp LSF1 glow. • Start/Running interlock occurs and TE/BE becomes to 0.	for simulating this test smoke was created by burning a paper in machine room after setting a loco speed through throttle	Checked in simulation mode from Both CAB Alarm triggered and warning smoke in machine room priority 1 fault message appeared on DDU screen. TE became zero	Verified OK	



Mr. Ankit Verma SSE/D&D/CLW/CRJ	Mr. Jitendra Singh Manager/R&D Hind Rectifiers Ltd.	Mr. Ashish Kumar Rathore SSE/TRS/BLEE	Mr. Kshaunish Kayal Manager/R&D Hind Rectifiers Ltd.	Mr. Pravin Panchal JE/TRS/BLEE	Mr. Jitendra Singh JE/D&D/CLW/CRJ
------------------------------------	--	---	---	--------------------------------------	--------------------------------------

Test Function	Test Procedure/ Functional Requirement	Test Procedure Followed	Observation	Result	Photo
	<p>than 62% of the full range because of a defective master controller</p> <p>Pop-Up message Fault in angle transmitter should be appeared on DDU</p> <p>Activate failure mode by moving the rotary switch 152 to position '1'</p> <p>Move reverser in forward/reverse direction</p> <p>Take Traction</p> <p>Angle transmitter must work at 3 steps i.e 1/3, 2/3 and max. values</p>		<p>active at 504 node state</p> <p>Disconnected EA connector from VCU 2 when CAB 2 was active</p> <p>After taking traction node was reached to 596. A pop-up message fault in angle transmitter was appeared on both DDU 1 (when CAB 1 is active) & DDU 2 (when CAB 2 is active)</p> <p>Angle transmitter moved at 3 steps i.e 1/3, 2/3 and max. values</p> <ul style="list-style-type: none"> With application of throttle, gradual increase in TE 		 <p>At 1/3TEmax < TE < 2/3TEmax</p>


					
Mr. Ankit Verma SSE/D&D/CLW/CRJ	Mr. Jitendra Singh Manager/R&D Hind Rectifiers Ltd.	Mr. Ashish Kumar Rathore SSE/TRS/BLEE	Mr. Kshaunish Kayal Manager/R&D Hind Rectifiers Ltd.	Mr. Pravin Panchal JE/TRS/BLEE	Mr. Jitendra Singh JE/D&D/CLW/CRJ





Test Function	Test Procedure/ Functional Requirement	Test Procedure Followed	Observation	Result	Photo
			<ul style="list-style-type: none"> has not observed Step change in values of TE/BE observed at position 1/3, 2/3, and maximum For TE minimal position from 0 to 1/3TEmax, TE observed is 138.3 KN For 1/3 TE_max up to 2/3 TE_max is 289.3 KN For 2/3TEmax up to full is 398.2KN <p>Regenerative braking in failure mode is working</p>		<p>At TE>2/3TEmax or TEmax</p> 


					
Mr. Ankit Verma SSE/D&D/CLW/CRJ	Mr. Jitendra Singh Manager/R&D Hind Rectifiers Ltd.	Mr. Ashish Kumar Rathore SSE/TRS/BLEE	Mr. Kshaunish Kayal Manager/R&D Hind Rectifiers Ltd.	Mr. Pravin Panchal JE/TRS/BLEE	Mr. Jitendra Singh JE/D&D/CLW/CRJ






Test Function	Test Procedure/ Functional Requirement	Test Procedure Followed	Observation	Result	Photo
					<p>AT 1/3BE max>BE> 0</p>  <p>AT 2/3BE max>BE> 1/3BE max</p> 


 Mr. Ankit Verma SSE/D&D/CLW/CRU	 Mr. Jitendra Singh Manager/R&D Hind Rectifiers Ltd.	 Mr. Ashish Kumar Rathore SSE/TRS/BLEE	 Mr. Kshaunish Kayal Manager/R&D Hind Rectifiers Ltd.	 Mr. Pravin Panchal JE/TRS/BLEE	 Mr. Jitendra Singh JE/D&D/CLW/CRU
---	--	--	---	--	---

Test Function	Test Procedure/ Functional Requirement	Test Procedure Followed	Observation	Result	Photo
Bogie Cut Out Mode	Single bogie isolation;	Firstly, VCB opened then one by one Bogie 1 & 2 isolated	Checked in both traction and simulation mode from both CAB	Verified OK	



					
Mr. Ankit Verma SSE/D&D/CLW/CRJ	Mr. Jitendra Singh Manager/R&D Hind Rectifiers Ltd.	Mr. Ashish Kumar Rathore SSE/TRS/BLEE	Mr. Kshaunish Kayal Manager/R&D Hind Rectifiers Ltd.	Mr. Pravin Panchal JE/TRS/BLEE	Mr. Jitendra Singh JE/D&D/CLW/CRJ

Test Function	Test Procedure/ Functional Requirement	Test Procedure Followed	Observation	Result	Photo
	Isolate any one bogie by rotary switch(154/SB1) to be kept in I/II(for isolation of SR1/SR2 position should be I/II) position and then isolation message should pop up on the DDU	through bogie cut out rotary switch For isolating SR1 through MCB, Firstly VCB opened then Tripped MCBs of SR1 127.1/1 & 127.11/1 in SB1 panel For isolating SR2 through MCB, Firstly VCB opened then Tripped MCBs of control electronics of SR2 127.1/2 & 127.11/2 in SB2 panel	After taking traction Priority 1 fault with Pop-Up message "Disturbance in converter" appeared on DDU LSFI and BPFA glowed in all cases After acknowledging BPFA faulty SR got isolated and LSFI lamp permanently glowed To do the faulty SR normal, MCE was reset.		



	Mr. Ankit Verma SSE/D&D/CLW/CRJ		Mr. Ashish Kumar Rathore SSE/TRS/BLEE		Mr. Kshaunish Kayal Manager/R&D Hind Rectifiers Ltd.		Mr. Pravin Panchal JE/TRS/BLEE		Mr. Jitendra Singh JE/D&D/CLW/CRJ
---	------------------------------------	--	--	---	--	---	-----------------------------------	---	--------------------------------------

Test Function	Test Procedure/ Functional Requirement	Test Procedure Followed	Observation	Result	Photo
					


 Mr. Ankit Verma SSE/D&D/CLW/CRU	 Mr. Jitendra Singh Manager/R&D Hind Rectifiers Ltd.	 Mr. Ashish Kumar Rathore SSE/TRS/BLEE	 Mr. Kshaunish Kayal Manager/R&D Hind Rectifiers Ltd.	 Mr. Pravin Panchal JE/TRS/BLEE	 Mr. Jitendra Singh JE/D&D/CLW/CRU
---	--	--	---	--	---

Test Function	Test Procedure/ Functional Requirement	Test Procedure Followed	Observation	Result	Photo
Configuration Mode		Loco was stand still with applied SA9 brake		Verified OK	 


 Mr. Ankit Verma SSE/D&D/CLW/CRJ	 Mr. Jitendra Singh Manager/R&D Hind Rectifiers Ltd.	 Mr. Ashish Kumar Rathore SSE/TRS/BLEE	 Mr. Kshaunish Kayal Manager/R&D Hind Rectifiers Ltd.	 Mr. Pravin Panchal JE/TRS/BLEE	 Mr. Jitendra Singh JE/D&D/CLW/CRJ
---	--	--	---	--	---

Test Function	Test Procedure/ Functional Requirement	Test Procedure Followed	Observation	Result	Photo
	<p>Rotary switch 160 to be moved at position 0</p> <p>Speed should be restricted to 15kmph</p> <p>Pop up message "Loco in shunting mode" should appear during every throttle movement</p>	<p>Throttle and reverser were in neutral position</p> <p>When node was 504 then shunting mode switch located in SB 1 moved from normal to active position</p>	<p>Checked in both simulation and power mode</p> <p>At 590 node throttle was taken</p> <p>After application of throttle loco is in shunting mode activated Pop-Up message is appeared.</p> <p>Maximum loco speed was reached up to 14.9 KMPH</p> <p>And Loco speed was restricted to 15 KMPH</p> <p>BPCS push button was pressed at 7.3 KMPH speed and loco speed became constant at 7.4 KMPH.</p>		 

	Mr. Ankit Verma SSE/D&D/CLW/CRJ		Mr. Ashish Kumar Rathore SSE/TRS/BLEE		Mr. Kshaunish Kayal Manager/R&D Hind Rectifiers Ltd.		Mr. Pravin Panchal JE/TRS/BLEE		Mr. Jitendra Singh JE/D&D/CLW/CRJ
---	------------------------------------	---	--	---	--	---	-----------------------------------	---	--------------------------------------

Test Function	Test Procedure/ Functional Requirement	Test Procedure Followed	Observation	Result	Photo
Vigilance Cut Out Mode	<p>Rotary Switch 237 to be kept at 0 position</p> <p>Speed to be increased and apply BPCS above 5kmph, no action to be taken for 1 minute</p> <p>VCD should not operate after 1 min</p> <p>Further rotary switch to be moved to original position '1' and check operation of VCD</p> <p>Pop up message of vigilance emergency applied should appear</p>	<p>When loco was in 504 node and SA9 was applied</p> <p>Moved VCD switch 237 located in SB 1 panel to 0 position</p>	<p>Checked in simulation mode from both CAB 1 and CAB 2</p> <p>At 590 node throttle was taken and node reached to 596. After 596 nodes, traction and speed appeared.</p> <p>When speed reached 11 KMPH BPCS push button was pressed and no action was taken for 1 minute.</p> <p>After 1-minute vigilance warning appeared.</p> <p>After 76 second vigilance emergency brakes were applied with popup on DDU.</p>	Verified OK	

	Mr. Ankit Verma SSE/D&D/CLW/CRIJ		Mr. Jitendra Singh Manager/R&D Hind Rectifiers Ltd.		Mr. Ashish Kumar Rathore SSE/TRS/BLEE		Mr. Kshaunish Kayal Manager/R&D Hind Rectifiers Ltd.		Mr. Pravin Panchal JE/TRS/BLEE		Mr. Jitendra Singh JE/D&D/CLW/CRIJ
---	-------------------------------------	---	---	--	--	---	--	---	-----------------------------------	---	---------------------------------------

Test Function	Test Procedure/ Functional Requirement	Test Procedure Followed	Observation	Result	Photo
Time, date & loco number	Ensure correct date time and loco number	Checked on DDU	Loco type WAG9 and loco number 38856 is displaying on DDU Time and date setting OS based. It is also suggested to add an indication for Hotel load converter in the DDU.	Verified OK	



					
Mr. Ankit Verma SSE/D&D/CLW/CRJ	Mr. Jitendra Singh Manager/R&D Hind Rectifiers Ltd.	Mr. Ashish Kumar Rathore SSE/TRS/BLEE	Mr. Kshaunish Kayal Manager/R&D Hind Rectifiers Ltd.	Mr. Pravin Panchal JE/TRS/BLEE	Mr. Jitendra Singh JE/D&D/CLW/CRJ

Annexure: 3

Protective Functions in WAG9 locomotive as per Document Vehicle Control System Software Specification F:3EHP 541 526

Description	Prescribed Value	Test Procedure Followed	Observation (Checked in Simulation/Traction Mode from Both CAB)	Remark	Photo
AC Primary Voltage (Cooling mode)	Trigger level 17.5 kV(RMS) (+/- 0.5 kV, no hysteresis) : VCB off	The trip setting was initiated by operating the MVR relay.	BL key was in C position, MCE was off	Verified OK	NA



					
Mr. Ankit Verma SSE/D&D/CLW/CRJ	Mr. Jitendra Singh Manager/R&D Hind Rectifiers Ltd.	Mr. Ashish Kumar Rathore SSE/TRS/BLEE	Mr. Kshaunish Kayal Manager/R&D Hind Rectifiers Ltd.	Mr. Pravin Panchal JE/TRS/BLEE	Mr. Jitendra Singh JE/D&D/CLW/CRJ






Description	Prescribed Value	Test Procedure Followed	Observation (Checked in Simulation/Traction Mode from Both CAB)	Remark	Photo
AC Primary Voltage (Driving mode)	Protective actions: 1) Minimum-voltage monitoring: $U \leq 17 \text{ kV(RMS)}$: VCB off closing of VCB inhibited if $U \leq 17.5 \text{ kV}$ 2) Maximum-voltage monitoring: $U \geq 30 \text{ kV(RMS)}$: VCB off closing of VCB inhibited if $U \geq 29 \text{ kV}$	For testing the protective action for the upper and lower limit of locomotive parameters Simulated forced signal was given to the controller of processor cards of the traction converter through software tool and GUI.	Values of OHE at which VCB tripped 1) VCB tripped for $U \leq 25 \text{ kV}$. (Actual value is 25 KV, forced value is 26 KV, Default value will be 17kV) 2) VCB tripped at $U \geq 31.5 \text{ kV}$, (Actual value is 25 KV Forced value is 24 KV. Default value will be 30kV) "Catenary voltage out of limit" Pop-Up message appeared on DDU	Verified OK	 



					
Mr. Ankit Verma SSE/D&D/CLW/CRJ	Mr. Jitendra Singh Manager/R&D Hind Rectifiers Ltd.	Mr. Ashish Kumar Rathore SSE/TRS/BLEE	Mr. Kshaunish Kayal Manager/R&D Hind Rectifiers Ltd.	Mr. Pravin Panchal JE/TRS/BLEE	Mr. Jitendra Singh JE/D&D/CLW/CRJ

Description	Prescribed Value	Test Procedure Followed	Observation (Checked in Simulation/Traction Mode from Both CAB)	Remark	Photo
AC Primary Current (Hardware Function)	Protective actions: 1) Trigger level 990 Apeak (+ 0 A / - 100 A): VCB off 2) Maximum-current monitoring during normal operation: Trigger level 360 ARMS (+ 0 A / - 20 A): VCB off		In cooling mode, MCE stays off due to which AC over current protection cannot be simulated through software logic AC over current protection in cooling mode is actuated by over current relay	Verified OK	AC over current protection in cooling mode is actuated by over current relay.



Mr. Ankit Verma SSE/D&D/CLW/CRJ	Mr. Jitendra Singh Manager/R&D Hind Rectifiers Ltd.	Mr. Ashish Kumar Rathore SSE/TRS/BLEE	Mr. Kshaunish Kayal Manager/R&D Hind Rectifiers Ltd.	Mr. Pravin Panchal JE/TRS/BLEE	Mr. Jitendra Singh JE/D&D/CLW/CRJ
------------------------------------	---	--	--	-----------------------------------	--------------------------------------

Description	Prescribed Value	Test Procedure Followed	Observation (Checked in Simulation/Traction Mode from Both CAB)	Remark	Photo
AC Primary Return Current	Protective actions: 1) Maximum-current monitoring within 1.25 sec after switch-on of VCB (inrush current of transformer): $1 \geq 800 \text{ A(RMS)}$: VCB off 2) Maximum-current monitoring during normal operation: $1 \geq 330 \text{ A(RMS)}$: VCB off	For testing the protective action for the upper and lower limit of locomotive parameters Simulated forced signal was given to the controller of processor cards of the traction converter through software tool and GUI.	Values of AC Primary Return Current at which VCB tripped 1) VCB tripped for $1 \geq 810 \text{ A}$ To simulate the condition, the level has been changed in forced value. (Actual value – 10A Forced value- 8A Default value – 810A 2) VCB tripped for $1 \geq 338 \text{ A}$ (Actual value – 10A Forced value- 5A Default value – 338A) "Primary overcurrent" Pop-Up message appeared on DDU.	Verified OK	 

					
Mr. Ankit Verma SSE/D&D/CLW/CRJ	Mr. Jitendra Singh Manager/R&D Hind Rectifiers Ltd.	Mr. Ashish Kumar Rathore SSE/TRS/BLEE	Mr. Kshaunish Kaval Manager/R&D Hind Rectifiers Ltd.	Mr. Pravin Panchal JE/TRS/BLEE	Mr. Jitendra Singh JE/D&D/CLW/CRJ



Description	Prescribed Value	Test Procedure Followed	Observation (Checked in Simulation/Traction Mode from Both CAB)	Remark	Photo
Harmonic Filter Current	Protective actions: 1) Maximum-current monitoring within 1 sec after switch-on of harmonic-filter: $I \geq 600 \text{ A(RMS)}$: VCB off, contactor harmonic filter off 2) Maximum-current monitoring during normal operation: $I \geq 410 \text{ A(RMS)}$: VCB off, contactor harmonic filter off	For testing the protective action for the upper and lower limit of locomotive parameters Simulated forced signal was given to the controller of processor cards of the traction converter through software tool and GUI.	Values of Harmonic Filter Current at which VCB tripped To simulate the condition, the level has been changed in forced value. 1) VCB tripped for 12600A (Actual value – 168A Forced value – 150A Default value – 600A) 2) VCB tripped for 12410A (Actual value – 190A Forced value – 130A Default value – 410A) Harmonic filter current too high Pop-Up message appeared on DDU.	Verified OK.	 



					
Mr. Ankit Verma SSE/D&D/CLW/CRJ	Mr. Jitendra Singh Manager/R&D Hind Rectifiers Ltd.	Mr. Ashish Kumar Rathore SSE/TRS/BLEE	Mr. Kshaunish Kayal Manager/R&D Hind Rectifiers Ltd.	Mr. Pravin Panchal JE/TRS/BLEE	Mr. Jitendra Singh JE/D&D/CLW/CRJ

Description	Prescribed Value	Test Procedure Followed	Observation (Checked in Simulation/Traction Mode from Both CAB)	Remark	Photo
Auxiliary Current	Protective actions: 1) Maximum-current monitoring: $I \geq 400 \text{ A(RMS)}$: VCB off	For testing the protective action for the upper and lower limit of locomotive parameters Simulated forced signal was given to the controller of processor cards of the traction converter through software tool and GUI.	Values of Auxiliary Current at which VCB tripped To simulate the condition, the level has been changed in forced value. VCB tripped at IZ402A (Actual value – 117A Forced value - 100A Default value – 400A) Auxiliary winding overcurrent Pop up message appeared on DDU	Verified OK.	 

Mr. Ankit Verma SSE/D&D/CLW/CRJ	Mr. Jitendra Singh Manager/R&D Hind Rectifiers Ltd.	Mr. Ashish Kumar Rathore SSE/TRS/BLEE	Mr. Kshaunish Kayal Manager/R&D Hind Rectifiers Ltd.	Mr. Pravin Panchal JE/TRS/BLEE	Mr. Jitendra Singh JE/D&D/CLW/CRJ
------------------------------------	---	---	---	--------------------------------------	--------------------------------------

Description	Prescribed Value	Test Procedure Followed	Observation (Checked in Simulation/Traction Mode from Both CAB)	Remark	Photo
Vehicle Speed, Motor Speed	Protective actions: 1) 100 <V <= 110 KM/PH TE linear reduction from 100 % to 0 % in VCU 2) v > 112 km/h : IGBT-pulsing inhibited		In simulation mode, when speed exceeded to 100 KM/PH, buzzer alarm activated, VCU start reducing TE demand with a linear reduction from 100 % to 0 % in VCU. When speed v> 113 km/h motor pulsing stopped.	Verified OK	

 Mr. Ankit Verma SSE/D&D/CLW/CRJ	 Mr. Jitendra Singh Manager/R&D Hind Rectifiers Ltd.	 Mr. Ashish Kumar Rathore SSE/TRS/BLEE	 Mr. Kshaunish Kayal Manager/R&D Hind Rectifiers Ltd.	 Mr. Pravin Panchal JE/TRS/BLEE	 Mr. Jitendra Singh JE/D&D/CLW/CRJ
---	--	---	--	---	---

Description	Prescribed Value	Test Procedure Followed	Observation (Checked in Simulation/Traction Mode from Both CAB)	Remark	Photo
Traction Motor Temperature	Protective actions: 1) IGBT-pulsing inhibited: 230 °C	For testing the protective action for the upper and lower limit of locomotive parameters Simulated forced signal was given to the controller of processor cards of the traction converter through software tool and GUI.	VCB tripped for motor temperature $T \geq 230^{\circ}\text{C}$ (Actual value – 21.8°C Forced value- 20°C Default value – 230°C)	Verified OK	 


Mr. Ankit Verma SSE/D&D/CLW/CRJ	Mr. Jitendra Singh Manager/R&D Hind Rectifiers Ltd.	Mr. Ashish Kumar Rathore SSE/TRS/BLEE	Mr. Kshaunish Kayal Manager/R&D Hind Rectifiers Ltd.	Mr. Pravin Panchal JE/TRS/BLEE	Mr. Jitendra Singh JE/D&D/CLW/CRJ
------------------------------------	---	--	--	-----------------------------------	--------------------------------------

	Mr. Ankit Verma SSE/D&D/CLW/CRJ		Mr. Jitendra Singh Manager/R&D Hind Rectifiers Ltd.		Mr. Ashish Kumar Rathore SSE/TRS/BLEE		Mr. Kshaunish Kayal Manager/R&D Hind Rectifiers Ltd.		Mr. Pravin Panchal JE/TRS/BLEE		Mr. Jitendra Singh JE/D&D/CLW/CRJ
---	------------------------------------	---	---	--	--	---	--	---	-----------------------------------	---	--------------------------------------



	Mr. Ankit Verma SSE/D&D/CLW/CRJ
	Mr. Jitendra Singh Manager/R&D Hind Rectifiers Ltd.
	Mr. Ashish Kumar Rathore SSE/TRS/BLEE
	Mr. Kshanaish Kayal Manager/R&D Hind Rectifiers Ltd.
	Mr. Pravin Panchal JE/TRS/BLEE
	Mr. Jitendra Singh JE/D&D/CLW/CRJ

[illegible]

Mr. Ankit Verma SSE/D&D/CLW/CRJ	Mr. Jitendra Singh Manager/R&D Hind Rectifiers Ltd.	Mr. Ashish Kumar Rathore SSE/TRS/BLEE	Mr. Kshaunish Kayel Manager/R&D Hind Rectifiers Ltd.	Mr. Pravin Panchal JET/TRS/BLEE	Mr. Jitendra Singh JE/D&D/CLW/CRJ
------------------------------------	---	--	--	------------------------------------	--------------------------------------




Description	Prescribed Value	Test Procedure Followed	Observation (Checked in Simulation/Traction Mode from Both CAB)	Remark	Photo
Converter Oil Temperature	Protective actions: 1) VCB Off: T 80°C longer than 10 sec	For testing the protective action for the upper and lower limit of locomotive parameters Simulated forced signal was given to the controller of processor cards of the traction converter through software tool and GUI.	When converter oil temperature exceeded the following results. VCB tripped at T=281 °C. Actual temp was 29.45 °C, limit changed to 25 °C. After One iteration particular bogie got isolated. "Converter oil temperature too high" Pop-Up message appeared on DDU.	Verified OK	

					
Mr. Ankit Verma SSE/D&D/CLW/CRJ	Mr. Jitendra Singh Manager/R&D Hind Rectifiers Ltd.	Mr. Ashish Kumar Rathore SSE/TRS/BLEE	Mr. Kshaunish Kayal Manager/R&D Hind Rectifiers Ltd.	Mr. Pravin Panchal JE/TRS/BLEE	Mr. Jitendra Singh JE/D&D/CLW/CRJ

Description	Prescribed Value	Test Procedure Followed	Observation (Checked in Simulation/Traction Mode from Both CAB)	Remark	Photo
DC Link Voltage Main Converter	Protective actions: Udc < 2500 V : DC-link Under Voltage Udc > 3200 V : DC Link Over Voltage	For testing the protective action for the upper and lower limit of locomotive parameters Simulated forced signal was given to the controller of the traction converter through software tool and GUI.	When DC link voltage dropped below and exceeded above the following values VCB tripped at Vs=2450V, limit change 2500-volt, actual value is 2000 volt. 2) VCB tripped at Vs=3199V, limit change 1500 volt, actual value is 1950. volt. Disturbance in Converter, Line Converter-1 Bogie-1 Isolated Pop-Up message appeared on DDU	Verified OK	 

					
Mr. Ankit Verma SSE/D&D/CLW/CRJ	Mr. Jitendra Singh Manager/R&D Hind Rectifiers Ltd.	Mr. Ashish Kumar Rathore SSE/TRS/BLEE	Mr. Kshaurish Kaval Manager/R&D Hind Rectifiers Ltd.	Mr. Pravin Panchal JE/TRS/BLEE	Mr. Jitendra Singh JE/D&D/CLW/CRJ

Mr. Ankit Verma SSE/D&D/CLW/CRU	Mr. Jitendra Singh Manager/R&D Hind Rectifiers Ltd.	Mr. Ashish Kumar Rathore SSE/TRS/BLEE	Mr. K-shaunish Koyal Manager/R&D Hind Rectifiers Ltd.	Mr. Pravin Panchal JE/TRS/BLEE	Mr. Jitendra Singh JE/D&D/CLW/CRU
------------------------------------	---	---	--	--------------------------------------	--------------------------------------

Description	Prescribed Value	Test Procedure Followed	Observation (Checked in Simulation/Traction Mode from Both CAB)	Remark	Photo
Earth Fault Auxiliary Circuit	Protective actions: Binary signal 0 : normal operation Binary signal 1 : diagnostic data set (DDS) 'earth fault auxiliary circuit'	To simulate this, in HB2 panel relay 89.2 A & B are shorted.	Earth Fault Auxiliary Circuit Pop-Up message appeared on DDU. As per shed, the E/F indication need to be incorporated in DDU.	Verified OK	
Earth Fault 415V/110V Circuit	Protective actions: Binary signal 0 : normal operation Binary signal 1 : diagnostic data set (DDS) 'earth fault 415V/110V circuit'	To simulate this, in HB1 panel, relay 89.5 A & B points are shorted.	Earth Fault 415V/110V Circuit Pop-Up message appeared on DDU. As per shed, the E/F indication need to be incorporated in DDU.	Verified OK	
Earth Fault Filter Circuit	Protective actions: Binary signal 0 : normal operation Binary signal 1 : diagnostic data set (DDS) 'earth fault filter circuit'	To simulate this, in FB Cubicle, relay 89.6 A & B points are shorted.	Earth fault harmonic filter circuit Pop-Up message appeared on DDU. As per shed, the E/F indication need to be incorporated in DDU.	Verified OK	

					
Mr. Ankit Verma SSE/D&D/CLW/CRJ	Mr. Jitendra Singh Manager/R&D Hind Rectifiers Ltd.	Mr. Ashish Kumar Rathore SSE/TRS/BLEE	Mr. Kshaunish Kayal Manager/R&D Hind Rectifiers Ltd.	Mr. Pravin Panchal JE/TRS/BLEE	Mr. Jitendra Singh JE/D&D/CLW/CRJ

Annexure: 4

Performance Testing & Commissioning Format For 3-Phase Locomotive fitted with IGBT based Traction Converter, Auxiliary Converter and VCU Format No. F60.305.01, Version:06

Description	Process followed to simulate the test	Observations	Result
Emergency stop in cooling mode	Raise panto in cooling mode. Put the brake controller into RUN position. Close the VCB. Push emergency stop button 244.	VCB got open Panto was lowered Emergency brake was applied	Verified OK
Emergency stop in driving mode	Raise panto in driving mode in. Put the brake controller into RUN position. Close the VCB. Push emergency stop button 244.	VCB got open Panto was lowered Emergency brake was applied	Verified OK
Shut down in cooling mode	Raise panto in cooling mode. Close the VCB. Bring the BL-key in 'O' position.	VCB got open Panto was lowered	Verified OK
Shut down in driving mode	Raise panto in driving mode. Close the VCB. Bring the BL-key in 'O' position.	VCB got open Panto was lowered	Verified OK
Interlocking pantograph-VCB in cooling mode	Raise panto in cooling mode. Close the VCB. Lower the pantograph by ZPT	VCB got open	Verified OK
Interlocking pantograph-VCB in driving mode	Raise panto in driving mode. Close the VCB. Lower the pantograph by ZPT	VCB got open	Verified OK

					
Mr. Ankit Verma SSE/D&D/CLW/CRJ	Mr. Jitendra Singh Manager/R&D Hind Rectifiers Ltd.	Mr. Ashish Kumar Rathore SSE/TRS/BLEE	Mr. Kshaunish Kayal Manager/R&D Hind Rectifiers Ltd.	Mr. Pravin Panchal JE/TRS/BLEE	Mr. Jitendra Singh JE/D&D/CLW/CRJ

Description	Process followed to simulate the test			Observations	Result
Measurement of protective shutdown by Converter 1 electronics	Start up the loco with both the converter. Raise panto. Close VCB. Move Reverser handle to forward or reverse. Remove one of the fiber optic/EMD/ESD/Communication media feedback cable from converter 1 Check that converter 1 electronics produces a protective shut down. <ul style="list-style-type: none"> VCB goes off Priority 1 fault msg. on DDU appears "Disturbance in Converter 1"			After removing the MVB cable from the Traction Converter 1 VCB goes OFF and fault msg popped up on DDU screen "Life sign from Line Converter 1 is missing"	Verified OK
Measurement of protective shutdown by Converter 2 electronics	Start up the loco with both the converter. Raise panto. Close VCB. Move Reverser handle to forward or reverse. Remove one of the fiber optic/EMD/ESD/Communication media feedback cable from converter 2. Check that converter 2 electronics produces a protective shut down. <ul style="list-style-type: none"> VCB goes off Priority 1 fault msg. on diagnostic display appears "Disturbance in Converter 2"			After removing the MVB cable from the Traction Converter 1 VCB was OFF and fault msg popped up on DDU screen "Life sign from Line Converter 2 is missing"	Verified OK
Cab activation in driving mode	No fault message should appear on the DDU of the loco.			No fault msg appeared on DDU screen	Verified OK
Check regenerative braking	Bring the TE/BE throttle to BE side. Loco speed should start reducing			Regenerative braking was checked during loco running in trial and found working satisfactory	Verified OK
Check for BUR redundancy test at ventilation level 1 & 3 of loco operation	In the event of failure of one BUR, rest of the two BURs can take the load of all the auxiliaries. For this switch off one BUR. Auxiliaries should be catered by rest of two BURs. Switch off the 2 BURs; loco should trip in this case.			BUR redundancy test was conducted with isolation of 1, 2 & 3 BUR individually. When 2 BURs were got isolated, main power SS01 also got isolated.	Verified OK

					
Mr. Ankit Verma SSE/D&D/CLW/CRU	Mr. Jitendra Singh Manager/R&D Hind Rectifiers Ltd.	Mr. Ashish Kumar Rathore SSE/TRS/BLEE	Mr. Kshaunish Kayal Manager/R&D Hind Rectifiers Ltd.	Mr. Pravin Panchal JE/TRS/BLEE	Mr. Jitendra Singh JE/D&D/CLW/CRU

Description	Process followed to simulate the test	Observations	Result
		"Disturbance in BUR Processor 1/2/3" pop-up message appeared. Power Supply of Traction Converter was isolated from SB1 & SB2 and VCB turned OFF Bogie 1 Isolated only half traction available. Moved BL key from off to drive position	
Check the power converter isolation test	Create disturbance in power converter by switching off the electronics. VCB should open and converter should get isolated and traction is possible with another power converter.	After self-test node reached to 504, after raising pantio node reached to 550, and after closing VCB node reached to 570 all auxiliaries start working MR, BP and FP are charged accordingly.	Verified OK
Loco charging.	Loco to be charged and all auxiliaries should run. No fault message to appear on the diagnostic panel of the loco. Raise MR pressure to 10 Kg/cm ² , BP to 5 Kg/cm ² , FP to 6 Kg/cm ² .	1-BLCP off mode verified compressor not operate. 2-Auto & Manual verified 3-Un-loader valve operated during ON of compressor 4-When MR pressure drops below 8 Kg/cm ² both compressor runs till MR pressure reached at 10 Kg/cm ² .	Verified OK
Check operation of compressors in "AUTO" Mode.	<ul style="list-style-type: none"> • BLCP off mode • Manual mode • Auto mode • At the starting of compressors un-loader valve should operate. • If MR pressure is less than 8 Kg/cm² both compressor will run till MR pressure reaches at 10 Kg/cm². 		Verified OK

					
Mr. Ankit Verma SSE/D&D/CLW/CRJ	Mr. Jitendra Singh Manager/R&D Hind Rectifiers Ltd.	Mr. Ashish Kumar Rathore SSE/TRS/BLEE	Mr. Kshaunish Kayal Manager/R&D Hind Rectifiers Ltd.	Mr. Pravin Panchal JE/TRS/BLEE	Mr. Jitendra Singh JE/D&D/CLW/CRJ

Description	Process followed to simulate the test	Observations	Result
		5-Low M/R pressure verified	
Check function of emergency push stop.	Emergency stop push button was pressed	It is working only in activated cab. By pressing Emergency stop push button, VCB opens & pantograph lowers Checked in both simulation and traction mode	Verified OK
Check function of BPCS.	Beyond 5 kmph, press BPCS, the speed of loco should be constant. BPCS action should be cancelled by moving TE/BE throttle, by dropping BP below 4.75 Kg/cm ² , by pressing BPCS again.	Below 5 KMPH it is not working. And beyond 5kmph it works as stated. At loco speed 9 KMPH BPCS Push button pressed and speed became constant. By moving throttle BPCS action got disabled	Verified OK
Check train parting operation of the locomotive.	Emergency RS cock at ALP side operated to drop the BP pressure LSAF should glow.	LSAF glowed BP pressure dropped, AFL gauge needle shoot up, and Buzzer sounds. auto flasher starts glowing, on DDU screen "Alarm chain pulling" message appeared, BC & BP pressure was decreased, after 1 minute P2 fault Pop-Up Message	Verified OK

					
Mr. Ankit Verma SSE/D&D/CLW/CRIJ	Mr. Jitendra Singh Manager/R&D Hind Rectifiers Ltd.	Mr. Ashish Kumar Rathore SSE/TRS/BLEE	Mr. Kshaunish Kayal Manager/R&D Hind Rectifiers Ltd.	Mr. Pravin Panchal JE/TRS/BLEE	Mr. Jitendra Singh JE/D&D/CLW/CRIJ







Description	Process followed to simulate the test	Observations	Result
		Alarm Chain Pulling was appeared on DDU. As per shed remark, AFL logic with logging has been implemented in the software but the necessary wiring as per MS needs to be done by CLW.	
Check vigilance operation of the locomotive.	Set the speed more than 1.5 kmph and ensure that brakes are released For 60 seconds do not press vigilance foot switch or sanding foot switch or TE/BE throttle then Buzzer should start buzzing. LSVW should glow continuously.	Buzzer sounds after 1 minute LSVW glows	Verified OK
Check start/run interlock	At low pressure of MR ($< 5.6 \text{ kg/cm}^2$). With direct loco brake applied. With automatic train brake applied (BP $< 4.75 \text{ kg/cm}^2$). With emergency cock (BP $< 4.75 \text{ Kg/cm}^2$).	Start/run interlock was simulated with all the four combinations	Verified OK
Check traction interlock	Switch off the brake electronics MCB 127.7 in SB2. The tractive/braking effort should ramp down, and BP reduces rapidly.	After MCB 127.7 in SB2 was switched off TE/BE & BP reduced to zero	Verified OK
Brake Blending Test	During the Regeneration failure the loco brakes will be applied in proportion to throttle position in BE mode	Checked in simulation and traction mode To simulate the test condition VCB was intentionally opened after taking the throttle in BE in loco running condition.	Verified OK


					
Mr. Ankit Verma SSE/D&D/CLW/CRL	Mr. Jitendra Singh Manager/R&D Hind Rectifiers Ltd.	Mr. Ashish Kumar Rathore SSE/TRS/BLEE	Mr. Kshaunish Kayal Manager/R&D Hind Rectifiers Ltd.	Mr. Pravin Panchal JE/TRS/BLEE	Mr. Jitendra Singh JE/D&D/CLW/CRL

Description	Process followed to simulate the test		Observations	Result
ZTEL to be switched on at 596 node	TE should be limited to 300kN after applying the brakes (applicable only to WAG-9H)		Loco brake was automatically applied without application of SA 9 brake. Checked in simulation mode at 596 node, after taking traction TE not exceeded to 298 KN	Verified OK
Transformer Oil Pressure Sensor Failure Test	Remove the sensor to detect the failure message on DDU screen. VCB turns OFF		Transformer oil pressure sensor cable (214.C/1) was disconnected from amplifier "Transformer oil temperature is not ok" Pop-Up message appeared on DDU and VCB tripped	Verified OK
Transformer Oil Temperature Sensor Failure Test	Remove the sensor to detect the failure message on DDU screen. VCB turns OFF		Transformer temperature sensor cable (210.5A) was disconnected from amplifier "Transformer oil temperature is not ok" Pop-Up message appeared on DDU and VCB tripped	Verified OK
Motor Temperature Sensor Failure Test	Remove 1,2,3 temperature sensor cable from TC1/TC2 and check whether that motor is isolated. Again, in case of three motor the Bogie gets isolated.		VCB Tripped, "Traction motor temperature too high" Pop-Up message appeared on DDU and respective motor got isolated. When all temperature sensor connectors of SR1/SR2 were disconnected from MCU processor card then that bogie got isolated.	Verified OK

					
Mr. Ankit Verma SSE/D&D/CLW/CRJ	Mr. Jitendra Singh Manager/R&D Hind Rectifiers Ltd.	Mr. Ashish Kumar Rathore SSE/TRS/BLEE	Mr. Kshaunish Kayal Manager/R&D Hind Rectifiers Ltd.	Mr. Pravin Panchal JE/TRS/BLEE	Mr. Jitendra Singh JE/D&D/CLW/CRJ







Description	Process followed to simulate the test			Observations	Result
VCU Reset	Press the VCU reset switch at 504 node. BP should not drop more than 4.65kg/cm ² . Control Electronics will get off and restart. 504 node should be reached.			VCU reset push button was pressed BP does not drop MCE reset occurred	Verified OK
Inching mode	Reverser to be kept at forward/reverse mode. Inching mode to be selected from DDU. Speed limit to be set at 0.5-1.5kmph Press ZTEL switch.			Checked in forward reverse direction, after configuring through DDU screen, ZTEL switch was set to on position After moving ZTEL switch in off position ZTEL operation got deactivated	Verified OK
Motor Speed Sensor Failure Test	Speed sensor connectors of Bogie 1 & 2 was disconnected from motor sensor units (MSUs processor cards) from TC1/TC2 and checked whether that motor is isolated. When 3 speed sensors of Bogie1 and Bogie 2 was isolated one by one then that Bogie got isolated.			After disconnecting motor speed sensor connectors, "Fault in speed sensor" pop-up message was appeared with VCB tripped, BPFA and LSI glowed, after acknowledging BPFA that motor got isolated. When 3 speed sensors of Bogie1 and Bogie 2 was isolated one by one then that Bogie got isolated.	Verified OK
Traction Converter Coolant Oil	Remove the sensor to detect the failure message on DDU screen. VCB turns OFF			TC Coolant MCB was turned off from HB panel to simulate the result	Verified OK

					
Mr. Ankit Verma SSE/D&D/CLW/CRJ	Mr. Jitendra Singh Manager/R&D Hind Rectifiers Ltd.	Mr. Ashish Kumar Rathore SSE/TRS/BLEE	Mr. Kshaunish Kayal Manager/R&D Hind Rectifiers Ltd.	Mr. Pravin Panchal JE/TRS/BLEE	Mr. Jitendra Singh JE/D&D/CLW/CRJ

Description	Process followed to simulate the test	Observations	Result
Pressure Sensor Failure Test			
Speed restricted to 100 KMPH when harmonic filter got isolated	<p>Cas-1 In simulation mode, harmonic filter isolation has created by simulating the condition of harmonic filter over current by giving the forced command to the controller of processor card through software tool and HMI.</p> <p>Case-2 Harmonic filter isolated fault was created by harmonic filter contactor stuck off fault. By releasing pressure of EPC contactor (8.1 & 8.2) through FB cock on pneumatic panel</p>	<p>In simulation mode, for the first case, VCB was tripped and "Harmonic filter current too high" pop-up message appeared. After closing the VCB and taking traction speed was restricted to 100 kmph</p> <p>In second case, harmonic filter was isolated, again VCB closed and when traction taken speed restricted to 100 kmph.</p> 	Verified OK
Banking mode operation	The brake pipe of rolling stock will not be charged by the banking loco, but it will be possible for the banking	Banking mode was tested in power mode. Throttle was applied to check the TE demand	Verified OK







Mr. Ankit Verma SSE/D&D/CLW/CRJ	Mr. Jitendra Singh Manager/R&D Hind Rectifiers Ltd.	Mr. Ashish Kumar Rathore SSE/TRS/BLEE	Mr. Kshaunish Kayal Manager/R&D Hind Rectifiers Ltd.	Mr. Pravin Panchal JE/TRS/BLEE	Mr. Jitendra Singh JE/D&D/CLW/CRJ

Description	Process followed to simulate the test	Observations	Result
	loco's driver to apply train brakes from banking loco in case of emergency. Throttle can be applied		
VCB Stuck ON	VCB Stuck OFF/ON by continually ON/OFF of BLDJ	No VCB stuck ON/OFF message observed	Verified OK
BPFA operation	Fault should acknowledge by pressing BPFA in any fault pop	Fault get acknowledge by pressuring BPFA switch.	Verified OK
AD-BLDJ operation	Raise panto in driving mode. Close the VCB by AD-BLDJ. To check the operation of Energy saving mode, the following steps to be followed: 1. First keep the BL in 'D' position, raise the panto and switch on VCB. 2. Ensured all BUR are in service, TE/BE is zero, BC applied and loco speed is zero. 3. Ensured Temperature of Transformer oil, Traction converter coolant and traction motor is less than 55 deg.C 4. Wait for 5 min, if all the above condition prevails, then loco should go to energy saving mode by switching OFF BUR-2 converter. 5. By moving TE/BE throttle, Energy saving mode will be deactivated.	VCB got open/close by AD-BLDJ switch	Verified OK
Performance of BURs during energy saving mode		Energy saving mode getting activated & deactivated. As per described condition.	Verified OK
Auxiliary load - Isolation test	1-tripped any one Compressor MCB 2-tripped any one Scavenge Blower	Performed by tripping MCB from HB-2 panel and only popup message observed no performance issue was observed.	Verified OK
Check sanding operation.	1-Reversal in forward 1,3, sanding valves should be activated.	Operated from CAB-2 found 1-Reversal in forward 1,3, sanding valves is activated.	Verified OK

					
Mr. Ankit Verma SSE/D&D/CLW/CRJ	Mr. Jitendra Singh Manager/R&D Hind Rectifiers Ltd.	Mr. Ashish Kumar Rathore SSE/TRS/BLEE	Mr. Kshaurish Kayal Manager/R&D Hind Rectifiers Ltd.	Mr. Pravin Panchal JE/TRS/BLEE	Mr. Jitendra Singh JE/D&D/CLW/CRJ

Mr. Ankit Verma SSE/D&D/CLW/CRJ	Mr. Jitendra Singh Manager/R&D Hind Rectifiers Ltd.	Mr. Ashish Kumar Rathore SSE/TRS/BLEE	Mr. Kishanish Koyal Manager/R&D Hind Rectifiers Ltd.	Mr. Pravin Panchal JE/TRS/BLEE	Mr. Jitendra Singh JE/D&D/CLW/CRJ
------------------------------------	---	---	---	--------------------------------------	--------------------------------------

Description	Process followed to simulate the test		Observations	Result
Inching Mode	In inching mode speed of locomotive verified at 0.5 KMPH to 1.5 KMPH.		Inching mode at 0.5 KMPH & 1.5KMPH verified ok	Verified ok
Constant Speed	Speed should maintain constant speed by pressing BPCS at above 5 KMPH		BPCS pressed at 5KMPH speed & observed speed maintain 5 KMPH.	Verified ok

	Mr. Ankit Verma SSE/D&D/CLW/CRJ		Mr. Jitendra Singh Manager/R&D Hind Rectifiers Ltd.		Mr. Ashish Kumar Rathore SSE/TRS/BLEE		Mr. Kshaunish Kayal Manager/R&D Hind Rectifiers Ltd.		Mr. Pravin Panchal JE/TRS/BLEE		Mr. Jitendra Singh JE/D&D/CLW/CRJ
---	------------------------------------	---	---	--	--	---	--	---	-----------------------------------	---	--------------------------------------

Joint Note

In compliance to CLW letter no. C-D&D/T/24(Part-IV)/Hirect, dated 21.09.2024 functionality and performance testing was done on 19.03.2025 and the observations are as follows:

1. The snapshot of software version which has been uploaded in the loco no. 38856 is as follow and the versions are -

Description		Software version
SR 1 software version	:	1006
SR 2 software version	:	2006
BUR1 software version	:	103
BUR2 software version	:	203
BUR3 software version	:	303
VCU 1 software version	:	1036
VCU 2 software version	:	2036
DDU1 software version	:	DDU_CAB11703.11
DDU2 software version	:	DDU_CAB11703.11



Mr. Ankit Verma SSE/D&D/CLW/CRJ	Mr. Jitendra Singh Manager/R&D Hind Rectifiers Ltd.	Mr. Ashish Kumar Rathore SSE/TRS/BLEE	Mr. Kshaunish Kayal Manager/R&D Hind Rectifiers Ltd.	Mr. Pravin Panchal JE/TRS/BLEE	Mr. Jitendra Singh JE/D&D/CLW/CRJ


2. Graphical user interface (GUI) to monitor the healthiness of each motor has been implemented in DDU and same has been verified. Also Screen shot of same is attached below for reference



3. Recordings of 43 critical signals as per RDSO letter no. EL/3.1.35/17 dated 28.04.2023 has been implemented. The storing is being done for 72 hours and it is being downloaded through Ethernet cable and the data displayed in Excel format which is provided as Annexure-AA. Further it is to be noted that there are 62 parameters altogether which is being recorded.
4. Logic for energy-saving scheme, based on RDSO Modification Sheet no. 0482, rev 1, has been provided. Further whenever energy saving mode gets activated, in pixy window of DDU the status of the ESM will be ON indicating "ESM (Energy Saving mode): ON" showing a pop up message of "Energy Saving Mode Activated".



Mr. Ankit Verma SSE/D&D/CLW/CRJ	Mr. Jitendra Singh Manager/R&D Hind Rectifiers Ltd.	Mr. Ashish Kumar Rathore SSE/TRS/BLEE	Mr. Kshaunish Kayal Manager/R&D Hind Rectifiers Ltd.	Mr. Pravin Panchal JE/TRS/BLEE	Mr. Jitendra Singh JE/D&D/CLW/CRJ



5. Against implementation of DPWCS ICD firm confirmed that they have MVB ports ready for integration. However, due to unavailability of DPWCS in the locomotive the logic can't be verified.
6. Against implementation of WTB ICD firm mentioned that they are using standard WTB gateway unit of M/S HaslerRail which is already been used by other propulsion manufacturer. Same has been verified in loco. It can't be verified because similar propulsion system of M/S Hind Rectifiers Limited propulsion is not available.
7. Firm has provided Trouble shooting and Maintenance manual with Fault diagnostic list and mentioned that Compliance with the protection scheme is in already include in the manual and design documents. Thus, firm intimated to refer the same. Also firm has provided a joint test report which has been witnessed by CLW.
8. On 19.03.2025, a testing was conducted with two locomotives placed back-to-back in regeneration mode. The trail was done in both up and down gradient available inside CLW. In the testing following was observed
 - a. On the day of testing it was fair and sunny and no rain was there.
 - b. In the up gradient the maximum tractive effort which was reached was 508kN and the maximum speed was 9.2kmph. Wheel Slip appeared sometime but no tripping of Traction converter had been observed.

Mr. Ankit Verma SSE/D&D/CLW/CRJ	Mr. Jitendra Singh Manager/R&D Hind Rectifiers Ltd.	Mr. Ashish Kumar Rathore SSE/TRS/BLEE	Mr. Kshaunish Kayal Manager/R&D Hind Rectifiers Ltd.	Mr. Pravin Panchal JE/TRS/BLEE	Mr. Jitendra Singh JE/D&D/CLW/CRJ




- c. In down gradient the maximum tractive effort which was reached was 520 KN and the maximum speed observed was 12 kmph. Wheel slip in down gradient was not observed and snapshot for the same is attached for reference.



Mr. Ankit Verma SSE/D&D/CLW/CRJ	Mr. Jitendra Singh Manager/R&D Hind Rectifiers Ltd.	Mr. Ashish Kumar Rathore SSE/TRS/BLEE	Mr. Kshaunish Kayal Manager/R&D Hind Rectifiers Ltd.	Mr. Pravin Panchal JE/TRS/BLEE	Mr. Jitendra Singh JE/D&D/CLW/CRJ

In addition to this the TE curve for complete testing period is attached for reference.



In view of above of it can be observed that slip slide control has been found satisfactory. Currently, the test is being conducted with two locomotives connected back-to-back in regeneration mode, with the loads being simulated. However, more precise tuning may be required to match actual service conditions during field trials.

Additionally, it is to be noted that due to speed and track limitations at CLW, the complete performance could not be assessed at higher speeds. Therefore, firm may be advised to conduct foot plating of the locomotive when it is dispatched from CLW. Furthermore, ELS/Shop-19/CLW may be instructed to carry out pre-dispatch tests as per the testing and commissioning format along with the modifications with the necessary MS issued by RDSO.

Mr. Ankit Verma SSE/D&D/CLW/CRJ	Mr. Jitendra Singh Manager/R&D Hind Rectifiers Ltd.	Mr. Ashish Kumar Rathore SSE/TRS/BLEE	Mr. Kshaunish Kayal Manager/R&D Hind Rectifiers Ltd.	Mr. Pravin Panchal JE/TRS/BLEE	Mr. Jitendra Singh JE/D&D/CLW/CRJ