Page 1 of 1

AMENDMENT NO.: 1018

AMM/3PL CLW/CRJ

Sub: Category Amendment for 3 phase Loco.

Please incorporate the following amendment sheet for the said loco. This is for your kind information and necessary action may please be taken from your end.

SL	PL. NO	CAT. NO. & DESCRIPTION	DRG/SPEC NO	UNIT	C&D NO	QTY/	q	TY/LOCO		
NO	T E. NO	CAT. NO. & DESCRIPTION	DRG/SPEC NO	Civit	CODINO	C&D NO	WAG-9HC	WAP-7	WAP-5	REMARKS
1	29940436	S/9/0062 Leather Bellow with Mounting Arrngt. and Hardware in a set	1209-01.018-024 Alt.1	03			1 Set	1 Set	NIL	
		Leather Bellows (single section)	1209.01.018.029 Alt.2	01	T205/039	6	6	6	NII	Drg Alt. No have been changed from '1' to '2' as per modification advice no. ELDD/QF/3PH/187 dated 01.03.2024 issued by Dy.CEE/D-I with immediate effect.
			All others remain	unch	anged.					
	Copy to: 1.CEE/LOCC	2.Dy.CME/ELB 3.D	y.CME/ELA 4.Dy.	CMM/	M-I 5.D	y.CEE/I&I	D/HWH	6. Dy.CE	E/I&D/DI	I 7.CQAM

Prepared by JE/D

Checked by SSE/D Issued by Oy CEE/D-II

Page 1 of 3
AMENDMENT NO.:1019

AMM/3PL CLW/CRJ

Sub: Category Amendment for 3 phase Loco.

Please incorporate the following amendment sheet for the said loco. This is for your kind information and necessary action may please be taken from your end.

SL		ar in a promission	DDG/SDTG NO		CODNO	QTY/	Q	TY/LOCO		REMARKS
NO	PL. NO	CAT. NO. & DESCRIPTION	DRG/SPEC NO	UNII	C&D NO	C&D NO	WAG-9HC	WAP-7	WAP-5	REWIARKS
1	29041041	R/9/0105 Helical Springs for WAG- 9HC	CLW/MS/3/SPEC./ ELDO-BOGIE/004 Alt.1	03			1 set	Nil	Nil	This category have been splitted into R/9/0105A and R/9/0105B for further procurement. Since material to be procured in set, hence tenders should be floated by clubbing of both PL Nos so that order of same quantity of primary & secondary spring should be placed on same firm. This is as per modification advice no. ELDD/3651/Pt.129 dated 05.03.2024 issued by Dy.CEE/D-I with immediate effect.
		R/9/0105A Secondary Helical Springs for WAG-9HC	CLW/MS/3/SPEC./ ELDO-BOGIE/004 Alt.1	03			1 set	Nil	Nil	New category have been generated and material to be procured in set with R/9/0105B, hence tenders should be floated by clubbing of both PL
2	New PL No.	Secondary Spring (outer)	IB 011-00842 Item 3	01	T222/042	8	8	Nil	Nil	Nos. so that order of same quantity of primary & secondary spring should be placed on same firm. This is as per modification advice no.
		Secondary Spring (Inner)	IB 011-00842 Item 1	01	T222/043	8	8	Nil	Nil	ELDD/3651/Pt.129 dated 05.03.2024 issued by Dy.CEE/D-I with immediate effect.
		R/9/0105B Primary Helical Springs for WAG-9HC	CLW/MS/3/SPEC./ ELDO-BOGIE/004 Alt.1	03			1 set	Nil	Nil	New category have been generated and material to be procured in set with R/9/0105A, hence tenders should be floated by clubbing of both PL
3	New PL No.	Primary Spring (outer)	IB 011-00843 Item 3	03	T222/044	24	24	Nit	Nil	Nos. so that order of same quantity of primary & secondary spring should be placed on same firm.
		Primary Spring (Inner)	IB 011-00843 Item 1	01	T222/045	24	24	Nil	Nil	This is as per modification advice no. ELDD/3651/Pt.129 dated 05.03.2024 issued by Dy.CEE/D-I with immediate effect.

S. Mondal os. os. 24 Prepared by JE/D

Checked by SSE/D Issued by 22.

Dy.CEE/D-II

Page 2 of 3 AMENDMENT NO.:1019

SL	PL. NO	CAT. NO. & DESCRIPTION	DRG/SPEC NO	UNIT	C&D NO	QTY/	Q	TY/LOCO		REMARKS
NO	PL. NO	CAT. NO. & DESCRIPTION	DRG/SPEC NO	UNII	Capino	C&D NO	WAG-9HC	WAP-7	WAP-5	REWARKS
4	29045034	R/9/0010 Helical Springs (for WAP-7)	CLW/MS/3/SPEC./ ELDO-BOGIE/004 Alt.1	03			Nil	1 set	Nil	This category have been splitted into R/9/0010A and R/9/0010B for further procurement. Since material to be procured in set, hence tenders should be floated by clubbing of both PL Nos so that order of same quantity of primary & secondary spring should be placed on same firm. This is as per modification advice no. ELDD/3651/Pt.129 dated 05.03.2024 issued by Dy.CEE/D-I with immediate effect.
	•	R/9/0010A Primary Helical Springs (for WAP-7)	CLW/MS/3/SPEC./ ELDO-BOGIE/004 Alt.1	03			Nil	1 set	Nil	New category have been generated and material to be procured in set with R/9/0010B, hence tenders should be floated by clubbing of both PL
5	New PL No.	PRIMARY SPRING(END AXLE)	1209.01.115-008 Alt.1	01	T222/006	16	Nil	16	Nil	Nos. so that order of same quantity of primary & secondary spring should be placed on same firm.
		PRIMARY SPRING MID. AXLE OUTER	1209-01.115-009 Alt.1	01	T222/008	8	Nil	8	Nil	This is as per modification advice no.ELDD/3651/Pt.129 dated 05.03.2024 issued by
		PRIMARY SPRING MID. AXLE INNER	1209-01.115-009 Alt.1	01	T222/040	8	Nil	8	Nil	Dy.CEE/D-I with immediate effect.
6	New PL No.	R/9/0010B Secondary Helical Springs (for WAP-7)	CLW/MS/3/SPEC./ ELDO-BOGIE/004 Alt.1	03			Nil	1 set	Nil	New category have been generated and material to be procured in set with R/9/0010A, hence tenders should be floated by clubbing of both PL Nos. so that order of same quantity of primary & secondary spring should be placed on same firm.
	140.	SECONDARY SPRING	1209-01.015-010 Alt.1	01	T222/010	8	Nil	8	Nil	This is as per modification advice no.ELDD/3651/Pt.129 dated 05.03.2024 issued by Dy.CEE/D-I with immediate effect.

S. Mondal 05.03.2024 Prepared by JE/D

Checked by SSE/D

Issuer Dy 3/2 c Dy.CEE/D-II

Page 3 of 3 AMENDMENT NO.:1019

SL	PL. NO	CAT. NO. & DESCRIPTION	ppc/spsc.No	UNIT	C&D NO	QTY/	Q	TY/LOCO		DELIANDE
NO	PL. NO	CAT. NO. & DESCRIPTION	DRG/SPEC NO	UNIT	Cad NO	C&D NO	WAG-9HC	WAP-7	WAP-5	REMARKS
7	29045022	R/10/0006 Helical Springs	CLW/MS/3/SPEC./ ELDO-BOGIE/004 Alt.1	03			Nil	Nil	1Set	This category have been splitted into R/10/0006A and R/10/0006B for further procurement. Since material to be procured in set, hence tenders should be floated by clubbing of both PL Nos so that order of same quantity of primary & secondary spring should be placed on same firm. This is as per modification advice no. ELDD/3651/Pt.129 dated 05.03.2024 issued by Dy.CEE/D-I with immediate effect.
8	New PL No.	R/10/0006A Primary Helical Springs for WAP-5	CLW/MS/3/SPEC./ ELDO-BOGIE/004 Alt.1	03		٠	Nil	Nil	15ot	New category have been generated and material to be procured in set with R/10/0006B, hence tenders should be floated by clubbing of both PL nos. so that order of same quantity of primary & secondary spring should be placed on same firm. This is as per modification advice no.
		Primary Springs	1210-01.115-007 Alt. 1	01	B222/006	16	Nil	Nil	16	ELDD/3651/Pt.129 dated 05.03.2024 issued by Dy.CEE/D-I with immediate effect.
9	New PL No.	R/10/0006B Secondary Helical Springs for WAP-5	CLW/MS/3/SPEC./ ELDO-BOGIE/004 Alt.1	03			Nil	Nil	1Set	New category have been generated and material to be procured in set with R/10/0006A, hence tenders should be floated by clubbing of both PL Nos. so that order of same quantity of primary & secondary should be placed on same firm. This is
		SECONDARY SPRING	1210-01.015-010 Alt. 1	01	B222/009	8	Nil	Nil	8	as per modification advice no.ELDD/3651/Pt.129 dated 05.03.2024 issued by Dy.CEE/D-I with immediate effect.
	Copy to: 1.CEE/LOCC) 2.Dy.CME/ELB 3.D	y.CMM/M-I 4.Dy.(CEE/I8	kD/HWH	5. Dy.0	CEE/I&D/DL	I 6	.CQAM	

S. Monchal os. os. 2024 Prepared by JE/D

Checked by SSE/D Issued of 2 e Dy. CEE/D-II

Page 1 of 1

AMENDMENT NO.: 1020

AMM/3PL CLW/CRJ

Sub: Category Amendment for 3 phase Loco.

Please incorporate the following amendment sheet for the said loco. This is for your kind information and necessary action may please be taken from your end.

SL	PINO	CAT. NO. & DESCRIPTION	DRG/SPEC NO U	UNIT	T C&D NO	QTY/				
NO			J. 10 10 10 10 10 10 10 10 10 10 10 10 10	J.	Cabillo	C&D NO	WAG-9HC	WAP-7	WAP-5	REMARKS
1	29162051	V/9/0010 T.T.Air Dryer	MP.0.01.00.06, Rev. 06, March 2021 or latest.	03			1 Set	1 Set.	1 Set	Specification No. have been updated as per modification advice no. ELDD/3606/Part-II dated 29.02.2024 issued by Dy.CEE/D-III with immediate effect.
		Twin Tower Air Dryer with Pre-Coolescer & Final Filter.	at a	01	T327/201 B327/175	1 .	1	1	1	

Copy to:					·····	
1.CEE/LOCO	2.Dy.CME/ELA	3.Dy.CMM/M-I	4.Dy.CEE/I&D/HWH	5. Dy.CEE/I&D/DLI	6.CQAM	

S.Mondal CE.03.LY Prepared by JE/D

Checked by SSE/D



Page 1 of 2

AMENDMENT NO.:1021

AMM/3PL CLW/CRJ

Sub: Category Amendment for 3 phase Loco.

Please incorporate the following amendment sheet for the said loco. This is for your kind information and necessary action may please be taken from your end.

SL	n. 110	CAT NO S DECEDIORION	ppc/spsc.vc		C&D NO	QTY/	Q	TY/LOCO		REMARKS
NO	PL. NO	CAT. NO. & DESCRIPTION	DRG/SPEC NO	UNII	C&D NO	C&D NO	WAG-9HC	WAP-7	WAP-5	REMARKS
1	29230081	S/9/0026 Copper pipe fittings for WAG-9HC for E-70 Brake System	CLW/MS/3/067 Alt4	03			1 set	Nil	Nil	Category updated as per modification advice no. ELDD/3606/PtIV dated 01.03.2024 issued by Dy.CEE/D-III with immediate effect. Notes: Procurable qty. is 50% of the total annual production target for 2024-25 and onward. Procurable qty. should be reviewed annually, considering qty. of Cat. No. S/9/0087 and actual ordering of brake system for 3-Phase Loco.
			All others remain	unch	anged.		<u> </u>			
2	New PL No.	S/9/0087 Copper pipe fittings for WAG-9HC for CCB System	CLW/MS/3/067 Alt4	03			1 set	Nil	Nil	New Category generated as per modification advice no. ELDD/3606/PtIV dated 01.03.2024 issued by Dy.CEE/D-III with immediate effect. Notes: Procurable qty. is 50% of the total annual production target for 2024-25 and onward. Procurable qty. should be reviewed annually, considering qty. of Cat. No. S/9/0026 and actual ordering of brake system for 3-Phase Loco.
		COPPER COUPLING 1/2"	1209-18.406-066 Ref. 2 Alt. 2	01	T327/237	7	7	Nil	Nil	
		COPPER COUPLING 3/8"	1209-18.406-066 Ref. 3 Alt. 2	01	T327/238	28	28	Nil	Nil	
		CU. COUPLING 1"	1209-18.406-066 Ref. 1 Alt. 2	01	T327/239	2	2	Nil	Nil	

S. Mondal ce.c3.24 Prepared by JE/D Checked by



Page 2 of 2 AMENDMENT NO.:1021

SL N. N.	CAT NO & DESCRIPTION	nno/snro no		COD NO	QTY/	Q	TY/LOCO		REMARKS
NO PL. NO	CAT. NO. & DESCRIPTION	DRG/SPEC NO	UNIT	C&D NO	C&D NO	WAG-9HC	WAP-7	WAP-5	REMARKS
	1 1/2" COPPER ELBOW	1209-18.406-068 Ref4 Alt. 2	01	T327/240	8	8	Nil	Nil	
3 2923499	S/11/0026 Copper pipe fittings for WAP-7 for E-70 Brake System	CLW/MS/3/067 Alt4	03			Nil	1 set	Nil	Category updated as per modification advice no. ELDD/3606/PtIV dated 01.03.2024 issued by Dy.CEE/D-III with immediate effect. Notes: Procurable qty. is 50% of the total annual production target for 2024-25 and onward. Procurable qty. should be reviewed annually, considering qty. of Cat. No. S/11/0087 and actual ordering of brake system for 3-Phase Loco.
		All others remain	unch	anged.					
4 New PL No.	Copper pipe tittings for	CLW/MS/3/067 Alt4	03			Nil	1 set	Nil	New Category generated as per modification advice no. ELDD/3606/PtIV dated 01.03.2024 issued by Dy.CEE/D-III with immediate effect. Notes: Procurable qty. is 50% of the total annual production target for 2024-25 and onward. Procurable qty. should be reviewed annually, considering qty. of Cat. No. S/11/0026 and actual ordering of brake system for 3-Phase Loco.
	COPPER COUPLING 1/2"	1209-18.406-066 Ref. 2 Alt. 2	01	H327/515	7	Nil	7	Nil	
	COPPER COUPLING 3/8"	1209-18.406-066 Ref. 3 Alt. 2	01	H327/516	34	Nil	34	Nil	
	CU. COUPLING 1"	1209-18.406-066 Ref. 1 Alt. 2	01	H327/517	2	Nil	2	Nil	
	1-1/2" COPPER ELBOW	1209-18.406-068 Ref4 Alt. 2	01	H327/518	8	Nil	8	Nil	
Copy to: 1.CEE/LC				&D/HWH	L	CEE/I&D/DL	L	.CQAM	L

S. Mc ndal 06.03.24 Prepared by JE/D

Checked by SSE/D Dy.CEE/D-II

DOC NO:ELDD/3646 Pt. DATE:11.03.2024

CATEGORY AMENDMENT FOR 3 PHASE LOCO

Page 1 of 2

AMENDMENT NO.:1022

AMM/3PL CLW/CRJ

Sub: Category Amendment for 3 phase Loco.

Please incorporate the following amendment sheet for the said loco. This is for your kind information and necessary action may please be taken from your end.

SL	PL. NO	CAT. NO. & DESCRIPTION	DRG/SPEC NO	HAUT	C&D NO	QTY/	Q	TY/LOCO		DEMARKS
NO	PENO	CAT. NO. & DESCRIPTION	DRG/SPEC NO	UNIT	Cab No	C&D NO	WAG-9HC	WAP-7	WAP-5	REMARKS
1	New PL No.	R/9/0159 HIGH TENSILE TRANSITION CB COUPLER (TOP OPERATED)WITH TOP LIFTING HOOK,TOP LIFTING ASSEMBLY & LINK FOR TOP OPERATION IN FITTED CONDITION BUT WITHOUT HIGH CAPACITY DRAFT GEAR, STRIKER BLOCK 7 SUSPENSION HOOK (FOR TR SCREW COUPLING) AS PER RDSO DRG.NO SK-DL-4809, ALTNIL OR LATEST ITEM NO.1 TO 8, 12 TO 14,35 TO 40 &42. EXCEPT ITEM NO 9 TO 11, 15 TO 34, 41,43 TO 45" For		03			1 set	Nil	Nil	
		Arrangement of High tensile Transition CB Coupler (Top Operated)	RDSO Specn.No. 56-BD-07 MA No.2 or Latest & RDSO Drg No. SK.DL-4809 Alt. Nil or Latest. Part Drawing No. SK-62724 Alt-23 or latest, SKDL-2496 Alt-6 or latest, SK-69508 Alt-4 or latest, SKDL-2494 Alt.17 or latest & SKDL-2495 Alt.12 or latest. CLW Drawing No. 1209-02.441-120 Alt. Nil or latest, 1209-02.441-121 Alt. 1 or latest, 1209-02.441-122 Alt. Nil or latest, 1209-18.406-358-009 Alt. Nil or latest, 1209-18.406-382-008 Alt. Nil or latest,	01	T320/078	2	2	Nil	Nil	Alt. No. of Drg. No.1209-02.441-12: have been changed from 'Nil' to '1' as per modification advice no. ELDD/3611/Pt. dated 07.03.2024 issued by Dy.CEE/D-III with immediate effect.

Prepared by



landed by Dy.CEE/D-II

Page 2 of 2 AMENDMENT NO.:1022

SL	PL. NO	CAT. NO. & DESCRIPTION	DDG/SDEC NO	LIBUT	COD NO	QTY/	q	TY/LOCO		DESARDIC
NO	PL. NO	CAL NO. & DESCRIPTION	DRG/SPEC NO	UNIT	C&D NO	C&D NO	WAG-9HC	WAP-7	WAP-5	REMARKS
2	29130311	R/9/0152 Top Operating Rods, Link & Hook for E-type CBC for WAG-9HC Loco.		03	0		1 Set	Nil	Nil	
		Operating rod assly-LH	1209-02.441-118 Alt.1	01	T320/062	2	2	Nil	Nil	Alt. No. of Drg. No.1209-02.441-118 have been changed from 'Nil' to '1' as per modification advice no. ELDD/3611/Pt. dated 07.03.2024 issued by Dy.CEE/D-III with immediate effect.
		Operating rod assly-RH	1209-02.441-123 Alt.2	01	T320/063	2	2	Nil	Nil	immediate effect. Alt. No. of Drg. No.1209-02.441-123 have been changed from 'Nil' to '2' as per modification advice no. ELDD/3611/Pt. dated 07.03.2024 issued by Dy.CEE/D-III with immediate effect.
	25	Operating rod middle	1209-02.441-119	01	T320/064	2	2	Nil	Nil	
1	Copy to: 1.CEE/LOCO	2.Dy.CME/ELF 3.Dy.CMM/M-I 4.D	y.CEE/I&D/HWH 5. Dy.CEE/I&	D/DLI	6.CQA	M	han ar muna			

S. Mondal Prepared by JE/D

Checked by SSE/D Issued by Dy.CEE/D-II

Page 1 of 1

AMENDMENT NO.:1026

AMM/3PL CLW/CRJ

Sub: Category Amendment for 3 phase Loco.

Please incorporate the following amendment sheet for the said loco. This is for your kind information and necessary action may please be taken from your end.

SL			nno (spre No		con No	QTY/	, a	TY/LOCO		REMARKS
NO	PL. NO	CAT. NO. & DESCRIPTION	DRG/SPEC NO	UNIT	C&D NO	C&D NO	WAG-9HC	WAP-7	WAP-5	REMIARKS
1	29 030018	R/9/0059 GEAR CASE COMPLETE								
	•	Gear Case Complete	1209-01 013-014 Alt. 8	01	T201/005	6	6	6		Alt. No. of Drg. No.1209-01.013-014 have been changed from '7' to '8' as per modification advice no. ELDD/3751/Pt./365 dated 15.03.2024 issued by Dy.CEE/D-I with immediate effect.
	Copy to: 1.CEE/LOCO	2.Dy.CME/ELB 3.Dy.CMM/M	I 4.Dy.CEE/i& D/ HWH	5. Dy.0	EE/I&D/DLI	6.0	CQAM			

S Mondal 20.03.24 Prepared by JE/D

Checked by SSE/D Issued by Dy.CEE/D-II

Page 1 of 1

AMENDMENT NO.:1027

AMM/3PL CLW/CRJ

Sub: Category Amendment for 3 phase Loco.

Please incorporate the following amendment sheet for the said loco. This is for your kind information and necessary action may please be taken from your end.

SL			•			QTY/	Q	TY/LOCO		REMARKS
NO	PL. NO	CAT. NO. & DESCRIPTION	DRG/SPEC NO	זואט	C&D NO	C&D NO	WAG-9HC	WAP-7	WAP-5	REMARKS
1	29170140	T/9/0005 St.Steel pressed sec.for WAG-9HC Loco	CLW/MS/3/038 Alt.11	03			1 set	Nil	Nil	Alteration No. of tender specification have been changed from Alt.10 to Alt.11 as per modification advice no. ELDD/3611/Pt. dated 20.03.2024 issued by <a "="" 10.1007="" doi.org="" href="https://doi.org/10.1007/journal.com/do</td></tr><tr><td></td><td></td><td>STD Tapping Plate</td><td>1209-18.430-230
Alt.2</td><td>01</td><td>T306/446</td><td>Nil</td><td>Nil</td><td>Nil</td><td>Nil</td><td>Item have been deleted from this Category as per modification advice no. ELDD/3611/Pt. dated 20.03.2024 issued by Dy.CEE/D-III with immediate effect.</td></tr><tr><td></td><td></td><td></td><td>All other items will</td><td>remai</td><td>in same</td><td></td><td></td><td></td><td></td><td></td></tr><tr><td>2</td><td>29741129</td><td>T/11/0005 Stainless Steel pressed section. for WAP-7 Loco(Hotel load converter based)</td><td>CLW/MS/3/038 Alt.11</td><td>03</td><td></td><td></td><td>Nil</td><td>1 set</td><td>Nil</td><td>Alteration No. of tender specification have been changed from Alt.10 to Alt.11 as per modification advice no. ELDD/3611/Pt. dated 20.03.2024 issued by Dy.CEE/D-III with immediate effect.
		STD Tapping Plate	1209-18.430-230 Alt.2	01	H306/624	Nil	Nil	Nil	Nil	Item have been deleted from this Category as per modification advice no. ELDD/3611/Pt. dated 20.03.2024 issued by Dy.CEE/D-III with immediate effect.
		<u>L</u>	All other items wil	l rema	in same		1			
	Copy to: 1.CEE/LOC	D 2.Dy.CME/ELA 3.D	Dy.CME/ELF 4.I	Dy.CN	1M/M-I	5.Dy.CEE	/I&D/HWH	6. Dy	.CEE/I&D	//DLI 7.CQAM 8.SSE/Document

S. Mondal 21.03.24 Prepared by JE/D Checked by SSE/D

Issued by Dy.CEE/D-II

Page 1 of 1
AMENDMENT NO.:1028

AMM/3PL CLW/CRJ

Sub: Category Amendment for 3 phase Loco.

Please incorporate the following amendment sheet for the said loco. This is for your kind information and necessary action may please be taken from your end.

CAT. NO. & DESCRIPTION R/9/0159 HIGH TENSILE TRANSITION CB COUPLER (TOP OPERATED)WITH TOP LIFTING HOOK, TOP LIFTING ASSEMBLY & LINK FOR TOP OPERATION IN FITTED CONDITION BUT WITHOUT HIGH CAPACITY DRAFT GEAR, STRIKER BLOCK & SUSPENSION HOOK (FOR TR SCREW COUPLING) AS PER RDSO DRG.NOSK-DL-4809, ALTNIL OR LATEST ITEM NO.1 TO 8, 12 TO 14,35 TO 40 &42. EXCEPT ITEM NO 9 TO 11, 15 TO 34, 41,43 TO 45" For WAG-9HC Locomotive.	DRG/SPEC NO	03	C&D NO	C&D NO	WAG-9HC	WAP-7	WAP-5	REMARKS
HIGH TENSILE TRANSITION CB COUPLER (TOP OPERATED)WITH TOP LIFTING HOOK, TOP LIFTING ASSEMBLY & LINK FOR TOP OPERATION IN FITTED CONDITION BUT WITHOUT HIGH CAPACITY DRAFT GEAR, STRIKER BLOCK & SUSPENSION HOOK (FOR TR SCREW COUPLING) AS PER RDSO DRG.NOSK-DL-4809, ALTNIL OR LATEST ITEM NO.1 TO 8, 12 TO 14,35 TO 40 &42. EXCEPT ITEM NO 9 TO 11, 15 TO 34, 41,43 TO		03			1 set	Nil	Nil	
~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~		- 3						
Area Company C	RDSO Specn.No. 56-BD-07 MA No.2 or Latest & RDSO Drg No. SK.DL-4809 Alt. Nil or Latest. Part Drawing No. SK-62724 Alt-23 or latest, SKDL-2496 Alt-6 or latest, SK-69508 Alt-4 or latest, SKDL-2494 Alt.17 or latest & SKDL-2495 Alt.12 or latest. CLW Drawing No. 1209-02.441-120 Alt. Nil or latest, 1209-02.441-121 Alt. 1 or latest, 1209-02.441-122 Alt. Nil or latest, 1209-18.406-358-009 Alt. 1 or latest, 1209-18.406-382-008 Alt. Nil or latest, 1209-18.406-488-011 Alt. Nil or latest & 1209-18.406-488-011 Alt. Nil or latest.	01	T320/078	2	2	Nil	Nil	Alt. No. of Drg. No.1209-18.40 358-009 have been changed from 'Nil' to '1' as per modification advice no. ELDD/3611/Pt. dated 21.03.2024 issued by <u>Dy.CEE/III</u> with immediate effect.
		Part Drawing No. SK-62724 Alt-23 or latest, SKDL-2496 Alt-6 or latest, SKDL-2496 Alt-6 or latest, SK-69508 Alt-4 or latest, SKDL-2494 Alt.17 or latest & SKDL-2495 Alt.12 or latest. CLW Drawing No. 1209-02.441-120 Alt. Nil or latest, 1209-02.441-121 Alt. 1 or latest, 1209-02.441-122 Alt. Nil or latest, 1209-18.406-358-009 Alt. 1 or latest, 1209-18.406-382-008 Alt. Nil or latest, 1209-18.406-488-011 Alt. Nil or latest	Part Drawing No. SK-62724 Alt-23 or latest, SKDL-2496 Alt-6 or latest, SKDL-2496 Alt-6 or latest, SK-69508 Alt-4 or latest, SKDL-2494 Alt.17 or latest & SKDL-2495 Alt.12 or latest. CLW Drawing No. 1209-02.441-120 Alt. Nil or latest, 1209-02.441-121 Alt. 1 or latest, 1209-02.441-122 Alt. Nil or latest, 1209-18.406-358-009 Alt. 1 or latest, 1209-18.406-382-008 Alt. Nil or latest, 1209-18.406-488-011 Alt. Nil or latest	Part Drawing No. SK-62724 Alt-23 or latest, SKDL-2496 Alt-6 or latest, SKDL-2494 Alt.17 or latest & SKDL-2495 Alt.12 or latest. CLW Drawing No. 1209-02.441-120 Alt. Nil or latest, 1209-02.441-121 Alt. 1 or latest, 1209-18.406-358-009 Alt. 1 or latest, 1209-18.406-382-008 Alt. Nil or latest, 1209-18.406-488-011 Alt. Nil or latest	Part Drawing No. SK-62724 Alt-23 or latest, SKDL-2496 Alt-6 or latest, SKDL-2494 Alt.17 or latest & SKDL-2495 Alt.12 or latest. CLW Drawing No. 1209-02.441-120 Alt. Nil or latest, 1209-02.441-122 Alt. Nil or latest, 1209-18.406-358-009 Alt. 1 or latest, 1209-18.406-382-008 Alt. Nil or latest, 1209-18.406-488-011 Alt. Nil or latest	Part Drawing No. SK-62724 Alt-23 or latest, SKDL-2496 Alt-6 or latest, SKDL-2494 Alt.17 or latest & SKDL-2495 Alt.12 or latest. CLW Drawing No. 1209-02.441-120 Alt. Nil or latest, 1209-02.441-122 Alt. Nil or latest, 1209-18.406-358-009 Alt. 1 or latest, 1209-18.406-382-008 Alt. Nil or latest, 1209-18.406-488-011 Alt. Nil or latest	Part Drawing No. SK-62724 Alt-23 or latest, SKDL-2496 Alt-6 or latest, SKDL-2494 Alt.17  Arrangement of High tensile Transition CB Coupler (Top Operated)  Coupler (Top Operated)  Drawing No. 1209-02.441-120 Alt. Nil or latest, 1209-02.441-122 Alt. Nil or latest, 1209-18.406-358-009 Alt. 1 or latest, 1209-18.406-382-008 Alt. Nil or latest, 1209-18.406-488-011 Alt. Nil or latest & \$1209-18.406-231 Alt. Nil or latest.	Part Drawing No. SK-62724 Alt-23 or latest, SKDL-2496 Alt-6 or latest, SKDL-2494 Alt.17 SK-69508 Alt-4 or latest, SKDL-2494 Alt.17 or latest & SKDL-2495 Alt.12 or latest. CLW Drawing No. 1209-02.441-120 Alt. Nil or latest, 1209-02.441-122 Alt. Nil or latest, 1209-02.441-122 Alt. Nil or latest, 1209-18.406-358-009 Alt. 1 or latest, 1209-18.406-382-008 Alt. Nil or latest, 1209-18.406-488-011 Alt. Nil or latest

5. Mandal 21.63.24 Prepared by JE/D Checked by SSE/D

Issued by Dy.CEE/D-II