

CATEGORY AMENDMENT FOR 3 PHASE LOCO

AMM/3PL
CLW/CRJ


Sub: Category Amendment for 3 phase Loco.


Please incorporate the following amendment sheet for the said loco. This is for your kind information and necessary action may please be taken from your end.										
SL NO	PL. NO	CAT. NO. & DESCRIPTION	DRG/SPEC NO	UNIT	C&D NO	QTY/ C&D NO	QTY/LOCO			REMARKS
							WAG-9HC	WAP-7	WAP-5	
1	29140225	V/9/0001A Brake Gear Arrngt. & Detail for WAG-9HC & WAP-7 loco		03			1 Set	1 Set	Nil	
		Brake Gear Arrngt. & detail for WAG-9HC & WAP-7 loco	1209-01.116-059 Alt.5 1209-01.216-060	01	T232/201 H232/201	1 Set	1 Set	1 Set	Nil	
		Brake Cylinder	01/3/19/56 Alt.11	01	T232/202 H232/202	8	8	8	Nil	Drg Alt. No. updated from Alt.10 to Alt.11 as per modification advice no. ELDD/3751/Pt.129 Vol.3 dated 21.11.2024 with immediate effect.
	All others remain unchanged.									

Copy to:

1.Dy.CME/ELB 2 .Dy.CMM/M-II 3. Dy.CMM/Depot 4. Dy.CEE/I&D/HWH 5. Dy.CEE/I&D/DLI 6. PE/Loco 7.SSE/Doc (Mech)

S. Mondal
23.11.2024
Prepared by
JE/D


23.11.24
Checked by
SSE/D


23/11/24
Reviewed by
AEE/D/Conv.


23/11/24
Issued by
Dy.CEE/D-III


AMM/3PL
CLW/CRJ


Sub: Category Amendment for 3 phase Loco.


Please incorporate the following amendment sheet for the said loco. This is for your kind information and necessary action may please be taken from your end.

SL NO	CAT NO	DESCRIPTION	DRG/SPEC NO	UNIT	C&D NO	QTY/ C&D NO	QTY/LOCO			REMARKS
							WAG-9HC	WAP-7	WAP-5	
1	R/9/0159 (PL No. 29130372)	"HIGH TENSILE TRANSITION CB COUPLER (TOP OPERATED) WITH TOP LIFTING HOOK, TOP LIFTING ASSEMBLY & LINK FOR TOP OPERATION IN FITTED CONDITION BUT WITHOUT HIGH CAPACITY DRAFT GEAR, STRIKER BLOCK & SUSPENSION HOOK (FOR TR SCREW COUPLING) AS PER RDSO DRG.NO.- SK-DL-4809, ALT.-NIL OR LATEST ITEM NO.1 TO 8, 12 TO 14,35 TO 40 & 42. EXCEPT ITEM NO.- 9 TO 11, 15 TO 34, 41,43 TO 45" For WAG-9HC Locomotive.		03			1 Set	Nil	Nil	
		Arrangement of High tensile Transition CB Coupler (Top Operated)	RDSO Specn.No. 56-BD-07 MA No.2 or Latest & RDSO Drg No.SK.DL-4809 Alt. Nil or Latest. Part Drawing No. SK-62724 Alt-23 or latest, SKDL-2496 Alt-6 or latest,SK-69508 Alt-4 or latest,SKDL-2494 Alt.17 or latest & SKDL-2495 Alt.12 or latest. CLW Drawing No. 1209-02.441-120 Alt. Nil or latest , 1209-02.441-121 Alt.1 or latest, <u>1209-02.441-122 Alt. 1 or latest</u> , 1209-18.406-358-009 Alt.1 or latest, 1209-18.406-382-008 Alt. Nil or latest, 1209-18.406-488-011 Alt. Nil or latest & 1209-18.406-231 Alt. Nil or latest.	01	T320/078	2	2	Nil	Nil	Alt. No. of Drawing no.1209-02.441-122 have been changed from 'Nil' to '1' as per modification advice no.ELDD/3611/Pt. dated 22.11.24 with immediate effect.
All others remain unchanged.										
Copy to:- 1.Dy.CME/ELA 2.Dy.CME/ELF 3.Dy.CEE/I&D/DLI 4.Dy.CEE/I&D/HWH 5.Dy.CMM/M-II 6.Dy.CMM/D 7.SSE/Doc(Mech)										

S. Mondal
26.11.24
Prepared by
JE/Drg


26.11.24
Checked by
SSE/Drg


26/11/2024
Reviewed by
SEE/Design.


26/11/24
Issued by
Dy.CEE/D-III

331