



Software Version Release Note

Bugs solved from v00_26 to v00_28

“The official updated version of this document can be found on the CAF POWER & AUTOMATION server. Any printed copy is an **UNCONTROLLED COPY.**”

Prepared by:	Reviewed by:	Approved by:
Ion Sagarzazu	Ion Sagarzazu	Juan Miguel Perez

© CAF POWER & AUTOMATION, S.L.

This document is the property of CAF POWER & AUTOMATION, S.L. and the information contained herein is confidential and shall not be used for any purpose other than the previously agreed purposes. Any reproduction, transmission or use of this document or of any of its contents is prohibited unless express written authorization from CAF POWER & AUTOMATION, S.L. is obtained.

Content

1. Edition Control.....	2
1.1. Edition Control.....	2
1.2. Distribution List	2
2. Software Release Definition	3
2.1. Implied Software Elements	3
2.2. Resolved Bugs.....	3

1. Edition Control

1.1. Edition Control

Edition	Description	Date
00_00	Bugs solved in SW version 00_28	01-06-2022

1.2. Distribution List

Person	Position	Company
Juan Miguel Perez	Traction Manager	CAF Power
Ion Sagarzazu	SAT Engineer	CAF Power
Parashuram Naganur	Manager field service	CAF Power
Rameshwar Goswami	SAT Engineer	CAF Power
Sanjay Ostwal	Project Manager	CGL
Krishan Junwani	CGL Engineer	CGL

2. Software Release Definition

2.1. Implied Software Elements

The new Release of this Software Element has the following dependencies:

<i>Project</i>	<i>Code</i>	<i>Description</i>
AA58	AA.58.91.0003	CJTO TRACCION WAG9
AA58	AA.58.91.0014	CJTO TRACCION WAG7

3. Resolved Bugs

3.1. SW_v00_28 (04/05/2022)

- Bug 193151: Wheel diameter management (no estimator, set to persistent).
- Bug 192802: Contactor Stuck ON Fatal and VCB isolation. The "Contactor stuck ON fatal" check was done only when the pantograph was up, now, the check is always done regardless of the pantograph position.

NOTE: This SW version has been generated from version 00_26 so the changes of SW version 00_27 do not apply.