

List of Electrically damaged vacant B/II type Quarters


Sl No	Street No	Quarter No	Type of Quarter	Remarks
1.	22	17A	B	
2.	22	50A	B	
3.	22	12A/B	B	
4.	22	7B	B	
5.	23	50B	B	
6.	24	67B	B	
7.	24	17A	B	
8.	26	15B	B	
9.	27	24B	B	
10.	27	46B	B	
11.	27	42A	B	
12.	27	8B	B	
13.	28	43B	B	
14.	28	46B	B	
15.	29	47B	B	
16.	29	40A	B	
17.	29	48B	B	
18.	29	49B	B	
19.	29	36A	B	
20.	29	29B	B	
21.	39	1B	B	
22.	40	33A	B	
23.	41	4B	B	
24.	41B	3B	B	
25.	72	2A	B	
26.	73	12A/B	B	
27.	72	5A	B	
28.	70	60B	B	
29.	69	6B	B	
30.	72	21A	B	
31.	73	21A	B	
32.	70	56A	B	
33.	73	3B	B	
34.	72	22B	B	
35.	72	3B	B	
36.	71	34A	B	
37.	73	17B	B	
38.	68	41B	B	
39.	66	7A	B	
40.	68	32B	B	
41.	70	3A	B	
42.	83	25/30B	II	

43.	83	25/23B	II	
44.	88	27B	II	
45.	84	23/18B	II	
46.	83	25/32B	II	
47.	88	28B	II	
48.	81	8A	II	
49.	81	25/30A	II	
50.	83	25/20/1A	II	
51.	86A	11B	II	
52.	82	23B	II	
53.	82	18/2B	II	
54.	85	3B	II	
55.	83	25/27A	II	
56.	82	18/6A	II	
57.	85	22B	II	
58.	81	7A	II	
59.	83	25A	II	
60.	88	28A	II	
61.	81	10B	II	
62.	85	27B	II	
63.	81	2B	II	
64.	85	29B	II	
65.	81	10B	II	
66.	86A	13A	II	
67.	83	21B	II	
68.	83	25/26B	II	
69.	85	4B	II	
70.	88	24B	II	
71.	84	23/14A	II	
72.	85	1/7A	II	
73.	83	5/28B	II	
74.	79	1A	II	
75.	82	18/5B	II	
76.	88	35B	II	
77.	81	23/14B	II	
78.	78	13B	II	
79.	80	10B	II	
80.	85	1/6A	II	
81.	82	15A	II	
82.	85	1/6B	II	
83.	86A	11A	II	
84.	85	1/5B	II	
85.	82	12/2B	II	
86.	83	25/22B	II	
87.	83	25/22A	II	
88.	84	5B	II	

89.	83	25/18B	II	
90.	80	14B	II	
91.	79	9B	II	
92.	88	22B	II	
93.	88	31A	II	
94.	81	13B	II	
95.	80	5A	II	
96.	83	25/21A	II	
97.	83	25/23A	II	
98.	51	12B	B	
99.	51	14A	B	
100.	54	16A	B	
101.	51	14B	B	
102.	55	15A	B	
103.	51	9A	B	
104.	54	15B	B	
105.	51	12A/B	B	
106.	54	12A	B	
107.	51	3A	B	
108.	82	1B	B	
109.	54	12B	B	
110.	83	40B	B	
111.	53	16B	B	
112.	83	34B	B	
113.	1A	4A	B	
114.	1A	14A	B	
115.	33B	34A	II	
116.	33B	23B	II	
117.	33B	22B	II	
118.	38B	11A	II	
119.	38B	20B	II	
120.	38B	12A/A	II	
121.	37A	14A	II	
122.	43A	11A	II	

Note : The above listed Quarters are in habitable condition on engineering point of view but **electrically damaged** declared by Electrical Department .

Employees willing to occupy the above Quarters in the same condition may take part in the Spot Allotment by submitting application within **17/07/2019**.


Ch OS/Quarter Section (W)
CLW/Chittaranjan